

VEHICLE REGISTER

REGISTRATION NUMBER:	161TOS	NHVAS Label Number:	A072198
Registered Owner:	McKenna Group Pty Ltd	Suby Y / ☒ N	
State of Registration:	QLD		
Vin Number:	JALFTR34LE7000008		
Manufacturer:	Isuzu		
Type of Unit:	Tip Truck		
Construction Date:	2014		
Tare Weight:	6740		
Date Joining NHVAS Maintenance	27/03/2015		
Date Leaving NHVAS Maintenance			
SCHEDULED SERVICE INTERVALS			
A.	10,000klms	B.	20,000klms
C.	200,000klms	D.	
Registered GVM/GCM	15000 : 24000		
Manufacturers GVM/GCM	15000 : 24000		
Date Joining NHVAS Mass			
Date Leaving NHVAS Mass			

(MUST BE COMPLETED FOR EACH UNIT)

Service Report Register
ISUZU TIP TRUCK
REGO 161TOS / NHVAS # A072198
UNIT# MCK40

Date	Service Report	HRS/KLMS	Description	Serviced By:
28/02/2014			Purchased From Brisbane Isuzu	
5/03/2014	674	366	Fit 2 way radio with power inverter	Lawrie Floyd
15/07/2015	2030	15736	Complete A & B Service. Replace LF Park Bulb.	Lawrie Floyd
27/03/2015			Joined NHVAS	
15/03/2016	2085	23255	Removed internal fan and filters cleared out as fan not operating properly	Lawrie Floyd
5/05/2016	2100	23628	Replaced number plate lights	Lawrie Floyd
5/05/2016	AS051	23628	Completed Annual Service	Lawrie Floyd
21/10/2016	2191	28907	Completed A, B & C Service. Replaced Bulbs In Water Tank Frame	Lawrie Floyd
5/05/2017	AS204	31427	Completed Annual Service	Andrew Brandt
5/06/2017	2119	34534	Completed A B & C Service. Fit new wiper blades, fit new flashing light	Andrew Brandt
4/05/2018	2261	44573	Completed A B & C Service.	Andrew Brandt
12/05/2018	AS224	44862	Completed Annual Inspection	Brendan McKenna
21/03/2019	2423	57518	Completed A Service. Needs a new retractable tarp soon as holes are getting bigger in the mesh	Matt Harries
1/05/2019	AS155	58717	Completed Annual Inspection	Brendan McKenna
16/01/2020	Inv 00045025	67949	Fit 2 New Tyres	Tim's Tyres
21/02/2020	3007	70123	Completed A B & C Service. Drain Valve On Air Tank repaired. Nitto fitting on air tank replaced	Matt Harries
5/05/2020	AS318	72506	Completed Annual Service	Matt Harries
25/09/2020	3032	81425	Completed A B & C Service.	Matt Harries
1/10/2020	Inv 00047681	82175	Fit 2 New Tyres - Pos 5 & 6	Tim's Tyres
29/04/2021	AS	92575	Completed Annual Service	Andrew Brandt
28/09/2021	3044	96396	C Service Completed	Andrew Brandt
16/10/2021	3056	96615	Diagnose air leak when park brake released. Fit new park brake replay. Make sure air builds up and no air leak	Andrew Brandt
20/05/2022	3078	103750	A Service Completed	Andrew Brandt
29/04/2022	Annual	102490	Completed Annual Inspection	Andrew Brandt
28/04/2023	3144	115697	Completed A B & C Service	Andrew Brandt
20/05/2023	Annual	115697	Completed Annual Inspection	Andrew Brandt
16/02/2024	3181	129300	Replace gearbox due to jumping out of 5th and couldn't get 6th. Fit new gearbox from Just Wrecking Isuzu	Andrew Brandt
8/04/2024	104630	130274	2 New Tyres Fitted	Total Tyres Auto
17/04/2024	G018434	131030	2 New Tyres Fitted	All Coast Tyres
29/04/2024	3199	131272	Completed C Service	Andrew Brandt
29/04/2024		131272	Completed Annual Inspection	Andrew Brandt
11/11/2024	1429		Air con Service	Luke James Auto Air
17/03/2025	3256	140895	Fit new radio head unit into truck. Fit new wiper blads, aircon was done as per fault 101670 on the 11/11/2024	Andrew Brandt
14/05/2025	3266	143315	Completed C Service	Andrew Brandt
			Replace fan belts. Fix fuel leak at tank. Replace supply and return fuel lines at tank	
14/05/2025	Annual		Completed Annual Inspection	Andrew Brandt
5/07/2025	107890		1 New Tyre	Total Tyres Auto
1/09/2025	3279	148718	Fit new UHF aerial	Andrew Brandt



BRENDAN MCKENNA
EARTHMOVING
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill QLD 4037
ABN 35 108 043 312

SERVICE REPORT No. S 3279

Day: Monday Date: 01/09/2025

MCKENNA GROUP
PTY LTD

Vehicle/Trailer: Isuzu	Rego: 161-TOS	MCK Unit No.	Kilms: 148,718km	Hours:
------------------------	---------------	--------------	------------------	--------

☐ A SERVICE CHECKLIST

☒ TRUCK (Approx 10,000km - 12,000km)

Check Fault/Repair Log and carry out necessary repairs.	Check brake system for leaks (service and main).
Grease all lubrication points.	Drain condensation from air units.
Lift cab/chassis, grease pivots, check condition and tension of bolts.	Check steering joints and linkages.
Check power steering for fluid levels and leaks.	Inspect for any obvious faults in suspension, structure or bodywork.
Check/top up engine oil and coolant level.	Visual check of airbag suspension where fitted.
Check transmission and differential for fluid levels and leaks.	Inspect wheel nuts and wheels for security, tyre for tread and inflation.
Check drive/ste and universal joints.	Check number plates, all labels for due date condition and security.
Check all lights and reflectors.	Check for visible exhaust emissions and leak of engine power.
Check horn, instruments, gauges, wipers and washers.	Fault #/s Rectified (if Applicable)
Check battery terminals and security.	
Inspect brake lining wear/level and adjust if required.	

☐ TRAILER (Approx 6 monthly/annually)

Grease all lubrication points.	Inspect for any obvious faults in suspension, structure or bodywork.
Inspect brake lining wear/level and adjust if required.	Visual check of airbag suspension where fitted.
Check all lights and reflectors.	Check number plates, and all labels due date, condition and security.
Check condition of air lines and electrical cable.	Re-torque all "U" bolts and cross members.
Inspect wheel nuts and wheels for security, tyre for tread and inflation.	Fault #/s Rectified (if Applicable)
Change oil in oil filled wheel bearings and check other wheel bearings.	

Notes:

Fit new UHF aerial.

☐ B SERVICE CHECKLIST Including Items from Checklist A

☒ TRUCK (Approx 20,000km)

All components of "X" service.	Check wear/movement in pinion arm, drag arm, tie rods and spring shackles.
Change engine oil and filter.	Replace or clean air cleaner as required.
Change fuel filters and bleed and check for leaks.	Check trailer breakaway and mast system.
Test coolant and change water filters if required.	
Check battery electrolyte level, terminals and security.	Fault #/s Rectified (if Applicable)
Check clutch linkage, clutch brake operation and adjustment.	
Check front steering hub oil level.	

☐ C SERVICE CHECKLIST Including Items from Checklist A and B

☐ TRUCK (Approx 200,000kms or annually)

All components of "X" and "B" services.	Change PTO Hydraulic filters.
Change power steering oil and filter.	Service air dryers where applicable.
Change transmission oil and filter (300000kms for Synthetic Oil).	Re-torque all "U" bolts and cross members.
Change differential oil and filter.	Fault #/s Rectified (if Applicable)
Change oil in oil filled wheel bearings, and check other wheel bearings.	
Check clutch linkage, clutch brake operation and adjustment.	

The person completing the service is to print their name and sign:

Name: Andrew Brandt

Signature: *Andrew Brandt*

Date: 01/09/2025

OFFICE USE ONLY Entered By: *Amber Smith*

Name:

Signature:

Date: 1.9.25

2 / 5 Lear Jet Drive
Caboolture Queensland 4510
ABN: 85660980414
Tel: 07 5499 1049
Fax: 07 5499 3643
Email: sales@taa.com.au
Website:
www.totaltyresandauto.com.au



TAX INVOICE

Tax Invoice Number: TTA - INV107890
Date: 05/07/2025
Due Date: 30/08/2025

BILL TO:

Brendan McKenna Earthmoving Pty-Ltd
11 Montego Court
Eatons Hill Queensland 4037
ABN: 94 163 887 563
Tel: Angela - 0418717154
Mobile: Brendon - 0417710806
Email: angela@mckgroup.com.au

FOR:

Punctured Left Front
Model: Isuzu FTR
Reg No: 161TOS
Fleet No: MCK40

Description	Qty.	Unit Price	GST	Amount
ONSITEPEWORKHRS - Onsite Callout Plant & Equipment - Work Hours Onsite Callout Plant & Equipment - Work Hours	1.0	\$99.00	\$9.00	\$99.00
BOLTONSPARETRU - Bolt on Spare Truck Tyre	1.0	\$30.00	\$2.73	\$30.00
TYREDISPOSAL-TB - Tyre Disposal - Truck Bus Tyre Disposal - Truck / Bus	1.0	\$27.50	\$2.50	\$27.50
LL27570225148145MF820 - Linglong 275/70R225 148/145M F820	1.0	\$390.00	\$35.45	\$390.00

Puncture was located on the inside wall 1 to 1.5 inches down from the tread crown. Unusual puncture in a position not repairable.

Fitted spare and ordered tyre to go onto spare wheel. Dropping to Red Road when fitted.

Subtotal	\$496.82
GST	\$49.68
Total	\$546.50
Paid	\$0.00
Balance Due	\$546.50

Please Note our Store Address has changed to 2/5 Lear Jet Drive Caboolture 4510.

Direct Deposit

BSB: 014309
ACC: 433109765

Please use your invoice number as your payment reference when paying via Direct deposit/bank transfer. Thank-you for your business.

The Tyre Product Stewardship Scheme is a government supported scheme focused on responsible tyre disposal, and the sustainable management of end-of-life tyres. We have been an active member of the scheme since January 2023. Together, we aim to change the way end-of-life tyres are managed and make our industry more environmentally sustainable.

Heavy Vehicle Inspection Checklist

This checklist is used to complete a vehicle inspection that meets maintenance management standard 4 criteria(4). The inspection must be completed or supervised by a suitably qualified person whose name and signature must appear on the form.

Registration #	161-TOS	Owner's Details	
Reason for Inspection	Annual Inspection	Inspection location	Beerburum
Inspection Date	14/05/2025	Make	Isuzu
Inspection Time	2pm	Model	FTR
Odometer	143,315km	VIN #	JALFTR34LE7000008
Registration Expiry Date	20/11/2025	Vehicle Colour	White

Cross out those items not applicable.

Tick for Pass Cross for Fail

Tick for Pass Cross for Fail

Item	Pass	N/a	Fail
Identification			
1 Registration Plates Affixed and Legible	☒	☐	☐
2 Compliance Plate Affixed	☒	☐	☐
Lights / Electrical			
3 Park / Tail / Number Plate / Clearance	☒	☐	☐
4 Head Lights / Auxiliary Lights	☒	☐	☐
5 Brake Lights	☒	☐	☐
6 Reflectors / Lenses	☒	☐	☐
7 Warning Device / Turning Indicators	☒	☐	☐
8 Wipers / Washers	☒	☐	☐
Glazing			
9 Material / Visibility	☒	☐	☐
10 Window Operation	☒	☐	☐
Seats / Seat Belts			
11 Mountings / Construction	☒	☐	☐
12 Fitting / Operation / Condition	☒	☐	☐
Wheels & Tyres			
13 Wheels / Security	☒	☐	☐
14 Wheel Bearings	☒	☐	☐
15 Tyres Tread Depth & Condition	☒	☐	☐
Body / Fittings/ Protrusions			
16 Corrosion / Security / Damage	☒	☐	☐
17 Door / Bonnet / Catches	☒	☐	☐
18 Rear Vision Mirrors	☒	☐	☐
19 Rear Marker Plates	☒	☐	☐
20 Body Fittings / Bumper Bars	☒	☐	☐
Tow Couplings			
21 Auto Tow Couplings	☒	☐	☐
22 King Pin / Skid Plate	☐	☒	☐
23 Tow Eye / Drawbar / Safety Chains	☐	☒	☐
24 Ball Race Turn Table	☐	☒	☐
25 Goose Neck	☐	☒	☐

Item	Pass	N/a	Fail
Braking			
26 Brake Components	☒	☐	☐
27 Brake Operation(Refer Notes)	☒	☐	☐
Steering			
28 Steering Box / Pitman Arm	☒	☐	☐
29 Arms / Linkages / Wheel	☒	☐	☐
30 King Pins	☒	☐	☐
31 Free Play	☒	☐	☐
Suspension			
32 Springs	☒	☐	☐
33 Hangers / Pins / Bushes	☒	☐	☐
34 Air Bags / Air Suspension	☐	☒	☐
35 Shock Absorbers	☒	☐	☐
36 Axles / Cross Members	☒	☐	☐
Oil / Fuel Leaks			
37 Engine / Driveline	☒	☐	☐
38 Steering / Accessories	☒	☐	☐
Exhaust			
39 Leaks / Design / Security	☒	☐	☐
40 Emissions	☒	☐	☐
Mountings			
41 Engine / Transmission	☒	☐	☐
42 Body	☒	☐	☐
Air Systems			
43 Leaks / Low Air Warning / Contamination	☒	☐	☐
44 Breakaway Protection	☒	☐	☐
Under body / Chassis			
45 Cracks / Security	☒	☐	☐
46 Corrosion	☒	☐	☐
Mudguards / Mud Flaps			
47 Fitted as Required	☒	☐	☐

Notes:

1. If manufacture specifications are unknown refer to the Heavy Vehicle Inspection Manual for minimum requirements.
2. For a heavy vehicle built after 1930, the service brake must bring the vehicle or combination to a stop within 16.5m from a speed of 35km/h.
3. Trailer breakaway protection must be checked for operation.

Name: Andrew Brandt

Signature: A Brandt



BRENDAN MCKENNA
EARTHMOVING
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill QLD 4037
ABN 35 108 043 312

SERVICE REPORT No. S 3266

Day: Wednesday Date: 14/05/2025

MCKENNA GROUP
PTY LTD

Vehicle/Trailer: Isuzu	Rego: 161-TOS	MCK Unit No. MCK40	Klms: 143,315km	Hours:
------------------------	---------------	--------------------	-----------------	--------

☒ A SERVICE CHECKLIST

☒ TRUCK (Approx 10,000km - 12,000km)	☒	☒
Check Fault/Repair Log and carry out necessary repairs.	☒	Check brake system for leaks (service and main).
Grease all lubrication points.	☒	Drain condensation from air tanks.
Lift cab/hopper, grease pivots, check condition and tension of belt.	☒	Check steering joints and linkages.
Check power steering for fluid levels and leaks.	☒	Inspect for any obvious faults in suspension, structure or bodywork.
Check/top up engine oil and coolant level.	☒	Visual check of airbag suspension where fitted.
Check transmission and differential for fluid levels and leaks.	☒	Inspect wheel nuts and wheels for security, tyres for tread and inflation.
Check drivehafe and universal joints.	☒	Check number plates, all labels for due date condition and security.
Check all lights and reflectors.	☒	Check for visible exhaust emissions and lack of engine power.
Check horn, instruments, gauges, mirrors and washers.	☒	Fault #/s Rectified (if Applicable)
Check battery terminals and security.	☒	
Inspect brake lining wear/towel and adjust if required.	☒	

☐ TRAILER (Approx 6 monthly/annually)

Grease all lubrication points.		Inspect for any obvious faults in suspension, structure or bodywork.
Inspect brake lining wear/towel and adjust if required.		Visual check of airbag suspension where fitted.
Check all lights and reflectors.		Check number plates and all labels due date, condition and security.
Check condition of air lines and electrical cables.		Re-torque all "U" bolts and strap members.
Inspect wheel nuts and wheels for security, tyres for tread and inflation.		Fault #/s Rectified (if Applicable)
Change oil in oil filled wheel bearings and check other wheel bearings.		

Notes:

Replace fan belts

Fix fuel leak at tank Replace supply and return fuel lines at tank

☒ B SERVICE CHECKLIST Including Items from Checklist A

☐ TRUCK (Approx 20,000km)	☒	☒
All components of "A" Service.	☒	Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.
Change engine oil and filters.	☒	Replace or clean air cleaner as required.
Change fuel filters and bleed and check for leaks.	☒	Check radiator breakaway and mesh system.
Test coolant and change water filters if required.	☒	
Check battery electrolyte level, terminals and security.	☒	Fault #/s Rectified (if Applicable)
Check clutch linkage, clutch brake operation and adjustment.	☒	
Check front steering hub all level.	☒	

☐ C SERVICE CHECKLIST Including Items from Checklist A and B

☐ TRUCK (Approx 200,000kms or annually)	☒	☒
All components of "A" and "B" Services.	☒	Change PTO Hydraulic filters.
Change power steering oil and filter.	☒	Service air dryer where applicable.
Change transmission oil and filter (300,000km for Synthetic Oil).	☒	Re-torque all "U" bolts and cross members.
Change differential oil and filter.	☒	Fault #/s Rectified (if Applicable)
Change oil in all fixed wheel bearings and check other wheel bearings.	☒	
Check clutch linkage, clutch brake operation and adjustment.	☒	

The person completing the service is to print their name and sign.

Name: Andrew Brandt

Signature: *Andrew Brandt*

Date: 14/05/2025

OFFICE USE ONLY Entered By: *Anthony Smith*

Name:

Signature: *Anthony Smith*

Date: 16/5/25



BRENDAN MCKENNA
EARTHMOVING
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

MCKENNA GROUP
PTY LTD

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

SERVICE REPORT No. S 3256

Day: Monday Date: 17/03/2025

Vehicle/Trailer: Isuzu	Rego: 161-TOS	MCK Unit No. Mck40	Kilms: 140,895km	Hours: N/A
------------------------	---------------	--------------------	------------------	------------

☐ **A SERVICE CHECKLIST**

☒ **TRUCK (Approx 10,000km - 13,000km)**

Check Fault Repair Log and carry out necessary repairs.	Check brake system for leaks (service and max).
Grease all lubrication points.	Drain condensation from air tanks.
Lift cab/hornet, grease pivots, check condition and tension of belts.	Check steering joints and linkages.
Check power steering for fluid levels and leaks.	Inspect for any obvious faults in suspension, structure or bodywork.
Check/top up engine oil and coolant level.	Visual check of airbag suspension where fitted.
Check transmission and differential for fluid levels and leaks.	Inspect wheel nuts and wheels for security, tyres for tread and inflation.
Check drive/line and universal joints.	Check number plates, all labels for due date condition and security.
Check all lights and reflectors.	Check for visible exhaust emissions and lack of engine power.
Check horn, instruments, gauges, wipers and washers.	Fault #/s Rectified (if Applicable)
Check battery terminals and security.	
Inspect brake lining wear/travel and adjust if required.	

☐ **TRAILER (Approx 6 monthly/annually)**

Grease all lubrication points.	Inspect for any obvious faults in suspension, structure or bodywork.
Inspect brake lining wear/travel and adjust if required.	Visual check of airbag suspension where fitted.
Check all lights and reflectors.	Check number plate, and all labels due date, condition and security.
Check condition of air lines and electrical cable.	Re-torque all "U" bolts and cross members.
Inspect wheel nuts and wheels for security, tyres for tread and inflation.	Fault #/s Rectified (if Applicable)
Change oil in oil filled wheel bearings and check other wheel bearings.	

Notes:

☐ **B SERVICE CHECKLIST Including items from Checklist A**

☒ **TRUCK (Approx 20,000km)**

All components of "A" service.	Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.
Change engine oil and filters.	Replace or clean air cleaner as required.
Change fuel filters and bleed and check for leaks.	Check trailer breakaway and max system.
Test coolant and change water filters if required.	
Check battery electrolyte level, terminals and security.	Fault #/s Rectified (if Applicable)
Check clutch linkage, clutch brake operation and adjustment.	
Check front steering hub oil level.	

☐ **C SERVICE CHECKLIST Including items from Checklist A and B**

☐ **TRUCK (Approx 200,000kms or annually)**

All components of "A" and "B" services.	Change PTO Hydraulic filters.
Change power steering oil and filter.	Service air dryers where applicable.
Change transmission oil and filter (300,000kms for Synthetic Oil).	Re-torque all "U" bolts and cross members.
Change differential oil and filter.	Fault #/s Rectified (if Applicable)
Change oil in oil filled wheel bearings and check other wheel bearings.	#102494 fit new radio head unit into truck fit new wiper blades, aircon was done as per fault 101670 on the 11/1/2024
Check clutch linkage, clutch brake operation and adjustment.	

The person completing the service is to print their name and sign.

Name: Andrew Brandt

Signature: *A Brandt*

Date: 17/03/2025

OFFICE USE ONLY. Entered By: *Amber Smith*

Name:

Signature: *Amber Smith*

Date: 18/3/25

TAX INVOICE

Brendan McKenna

Invoice Date
11 Nov 2024

Invoice Number
INV-1429

Reference
Isuzu 900

ABN
78 667 514 285

Luke James Auto Air
Pty Ltd
1670 Maleny Stanley
River Road
BOOROOBIN QLD
4552
AUSTRALIA

Description	Quantity	Unit Price	GST	Amount AUD
On-site labor (Luke)	3.00	110.00	10%	330.00
Work carried out 30/10/24 - 4/11/24				
Isuzu 900 161 TOS				
- Recover remaining refrigerant 250G - Blower Motor failure - Evaporator blocked - Fan belt loose - Idler bearing noisy				
- Replace blower motor, PWM control (supplied by Andrew) - Tighten fan belt - Replace idler bearing - Replace Dessicant bag - Vac, leak check and re-gas				
134A	0.25	105.00	10%	26.25
FDR Desiccant Bag	1.00	58.69	10%	58.69
UV Dye	1.00	15.70	10%	15.70
Cable ties, flush solution, o-rings, idler bearing ect	1.00	25.00	10%	25.00
Travel @ \$1.25 PER KLM	1.00	1.25	10%	1.25
Subtotal				456.89
TOTAL GST 10%				45.70
TOTAL AUD				502.59

Due Date: 18 Nov 2024
LJ AUTO AIR PTY LTD

BSB: 084-034
ACC#: 31-099-2703

Heavy Vehicle Inspection Checklist

This checklist is used to complete a vehicle inspection that meets maintenance management standard 4 criteria(4). The inspection must be completed or supervised by a suitably qualified person whose name and signature must appear on the form.

Registration # 161-TOS
Reason for Inspection Annual Inspection
Inspection Date 29/04/2024
Inspection Time 7am
Odometer 131,272km
Registration Expiry Date 20/11/2024

Owner's Details
Inspection location Red Road, Beerburum
Make Isuzu
Model FTR
VIN # JALFTR34LE7000008
Vehicle Colour

Cross out those items not applicable.

Tick for Pass Cross for Fail

Item	Pass	N/a	Fail
Identification			
1 Registration Plates Affixed and Legible	☒	☐	☐
2 Compliance Plate Affixed	☒	☐	☐
Lights / Electrical			
3 Park / Tail / Number Plate / Clearance	☒	☐	☐
4 Head Lights / Auxiliary Lights	☒	☐	☐
5 Brake Lights	☒	☐	☐
6 Reflectors / Lenses	☒	☐	☐
7 Warning Device / Turning Indicators	☒	☐	☐
8 Wipers / Washers	☒	☐	☐
Glazing			
9 Material / Visibility	☒	☐	☐
10 Window Operation	☒	☐	☐
Seats / Seat Belts			
11 Mountings / Construction	☒	☐	☐
12 Fitting / Operation / Condition	☒	☐	☐
Wheels & Tyres			
13 Wheels / Security	☒	☐	☐
14 Wheel Bearings	☒	☐	☐
15 Tyres Tread Depth & Condition	☒	☐	☐
Body / Fittings/ Protrusions			
16 Corrosion / Security / Damage	☒	☐	☐
17 Door / Bonnet / Catches	☒	☐	☐
18 Rear Vision Mirrors	☒	☐	☐
19 Rear Marker Plates	☒	☐	☐
20 Body Fittings / Bumper Bars	☒	☐	☐
Tow Couplings			
21 Auto Tow Couplings	☒	☐	☐
22 King Pin / Skid Plate	☐	☒	☐
23 Tow Eye / Drawbar / Safety Chains	☐	☒	☐
24 Ball Race Turn Table	☐	☒	☐
25 Goose Neck	☐	☒	☐

Tick for Pass Cross for Fail

Item	Pass	N/a	Fail
Braking			
26 Brake Components	☒	☐	☐
27 Brake Operation(Refer Notes)	☒	☐	☐
Steering			
28 Steering Box / Pitman Arm	☒	☐	☐
29 Arms / Linkages / Wheel	☒	☐	☐
30 King Pins	☒	☐	☐
31 Free Play	☒	☐	☐
Suspension			
32 Springs	☒	☐	☐
33 Hangers / Pins / Bushes	☒	☐	☐
34 Air Bags / Air Suspension	☐	☒	☐
35 Shock Absorbers	☒	☐	☐
36 Axles / Cross Members	☒	☐	☐
Oil / Fuel Leaks			
37 Engine / Driveline	☒	☐	☐
38 Steering / Accessories	☒	☐	☐
Exhaust			
39 Leaks / Design / Security	☒	☐	☐
40 Emissions	☒	☐	☐
Mountings			
41 Engine / Transmission	☒	☐	☐
42 Body	☒	☐	☐
Air Systems			
43 Leaks / Low Air Warning / Contamination	☒	☐	☐
44 Breakaway Protection	☒	☐	☐
Under body / Chassis			
45 Cracks / Security	☒	☐	☐
46 Corrosion	☒	☐	☐
Mudguards / Mud Flaps			
47 Fitted as Required	☒	☐	☐

Notes:

1. If manufacture specifications are unknown refer to the Heavy Vehicle Inspection Manual for minimum requirements.
2. For a heavy vehicle built after 1930, the service brake must bring the vehicle or combination to a stop within 16.5m from a speed of 35km/h.
3. Trailer breakaway protection must be checked for operation.

Name: Andrew Brandt

Signature: 



MCKENNA GROUP
PTY LTD

BRENDAN MCKENNA
EARTHMOVING
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

SERVICE REPORT No. S 3199

Day: Monday Date: 29/04/2024

Vehicle/Trailer: Isuzu	Rego: 161-TOS	MCK Unit No. Mck40	Klms: 131,272km	Hours: N/A
------------------------	---------------	--------------------	-----------------	------------

☒ A SERVICE CHECKLIST

☒ TRUCK (Approx 10,000km - 12,000km)	☒	☒	☒
Check Fault Repair Log and carry out necessary repairs.	☒	Check brake system for leaks (service and max).	☒
Grease all lubrication points.	☒	Drain condensation from air tanks.	☒
Lift cab/bonnet, grease pivots, check condition and tension of belts.	☒	Check steering joints and linkages.	☒
Check power steering for fluid levels and leaks.	☒	Inspect for any obvious faults in suspension, structure or bodywork.	☒
Check/top up engine oil and coolant level.	☒	Visual check of airbag suspension where fitted.	☒
Check transmission and differential for fluid levels and leaks.	☒	Inspect wheel nuts and wheels for security.	☒
Check driveline and universal joints.	☒	Check for tread and inflation.	☒
Check all lights and reflectors.	☒	Check number plates, all labels for due date condition and security.	☒
Check horn, instruments, gauges, wipers and washers.	☒	Check for visible exhaust emissions and lack of engine power.	☒
Check battery terminals and security.	☒	Fault #/s Rectified (If Applicable)	☒
Inspect brake lining wear/travel and adjust if required.	☒		☒

☐ TRAILER (Approx 6 monthly/annually)

Grease all lubrication points.		Inspect for any obvious faults in suspension, structure or bodywork.	
Inspect brake lining wear/travel and adjust if required.		Visual check of airbag suspension where fitted.	
Check all lights and reflectors.		Check number plate, and all labels due date, condition and security.	
Check condition of air lines and electrical cable.		Re-torque all "U" bolts and cross members.	
Inspect wheel nuts and wheels for security, tyres for tread and inflation.		Fault #/s Rectified (If Applicable)	
Change oil in oil filled wheel bearings and check other wheel bearings.			

Notes:

☒ B SERVICE CHECKLIST Including items from Checklist A

☒ TRUCK (Approx 20,000km)	☒	☒	☒
All components of "A" Service.	☒	Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.	☒
Change engine oil and filters.	☒	Replace or clean air cleaner as required.	☒
Change fuel filters and bleed and check for leaks.	☒	Check trailer breakaway and max system.	☒
Test coolant and change water filters if required.	☒		
Check battery electrolyte level, terminals and security.	☒	Fault #/s Rectified (If Applicable)	
Check clutch linkage, clutch brake operation and adjustment.	☒		
Check front steering hub oil level.	☒		

☒ C SERVICE CHECKLIST Including items from Checklist A and B

☒ TRUCK (Approx 200,000kms or annually)	☒	☒	☒
All components of "A" and "B" Services.	☒	Change PTO Hydraulic filters.	☒
Change power steering oil and filter.	☒	Service air dryers where applicable.	☒
Change transmission oil and filter (300,000km for Synthetic Oil).	☒	Re-torque all "U" bolts and cross members.	☒
Change differential oil and filter.	☒	Fault #/s Rectified (If Applicable)	
Change oil in oil filled wheel bearings and check other wheel bearings.	☒		
Check clutch linkage, clutch brake operation and adjustment.	☒		

The person completing the service is to print their name and sign.

Name: Andrew Brandt

Signature: *Andrew Brandt*

Date: 29/04/2024

OFFICE USE ONLY Entered By:

Name:

Amendola Smith

Signature:

Amendola Smith

Date: 1.5.24

All Coast Tyre Solutions - Gympie

50/56 Mellor Street
Gympie QLD 4570
Ph: (07) 5482 6633

Fax:

E-mail: gympie@allcoasttyres.com.au

Jaxport Pty Ltd ATF Yandina Unit Trust - All Coast Tyre Solutions

ABN: 18 718 867 756



Tax Invoice G018434

Date: 17 Apr 24

Customer: BRENDANMCKENNAEARTHMOVING
BRENDAN McKENNA EARTHMOVING
11 MONTEGO COURT
EATONS HILL QLD 4037

Terms: 30 Days from Statement

Written By: Craig Mattingley
Salesperson:

Deliver To: SAME

Contact: Brendan
Mobile: 0417 710 806 Home Ph:
Bus Ph: Fax:
Email: accounts@mckgroup.com.au
Odometer In: 131030 Out: 131030
Vehicle Details: Mck40

Customer PO#:

Item	Description	QTY	Unit Price (Excl GST)	Unit Price (Incl GST)	Total (Incl GST)
HA27570R225101	HAULMAX 275/70R22.5 144/141M ATT101	2	368.18	405.00	810.00
AS_6459998	Service Call - Business Hours (Per Hour)	1.5	132.73	146.00	219.00
XX_0053702	Disposal of Casing - Truck Tyre	2	27.27	30.00	60.00
AS_6549997	Fitting - Truck Tyre Steel wheel	2	27.27	30.00	60.00

Payment Method: OnAccount=1149.00

BANK DETAILS

Account Name ALL COAST TYRE SOLUTIONS

BSB: 064014

Account No. 10040117

Please include your CUSTOMER ID as your Ref.

Total includes GST of 104.45

Totals Items 2

Total \$

1149.00

Customer Service Policy: As we are committed to making our customer feel important, we have procedures in place to insure that we achieve this goal including:
Warranty provisions Customer Service Standards Quality Management Systems Customer Complaints System
If you require further information or if you are dissatisfied for any reason, please speak to your local store manager, or phone the Customer Service Manager on 1800 809 625 or write to the Customer Service Manager P.O. Box 479, Carlton South Vic. 3053.

Terms and Conditions of Trade: These goods are sold in accordance with Tyre Marketers (Australia) Limited's terms and conditions of sale (02/01). All payments are to be made in full, without any deduction of any nature, including by way of set-off. Property in products shall not pass until payment in full in cleared funds of all monies monies owed for those products or any other basis. Acceptance of these goods implies acceptance of such conditions.

Received by:

Date:

Completed: 17 Apr 24 4:39 PM

Last Printed: 4:39 PM

Page: 1

1 / 10 Lear Jet Drive
Caboolture Queensland 4510
ABN: 85660980414
Tel: 07 5499 1049
Fax: 07 5499 3643
Email: sales@taa.com.au
Website:
www.totaltyresandauto.com.au

22/4 AY



TAX INVOICE

Tax Invoice Number: TTA - INV104630
Date: 08/04/2024
Due Date: 30/05/2024

BILL TO:

Brendan McKenna Earthmoving Pty-Ltd
11 Montego Court
Eatons Hill Queensland 4037
ABN: 94 163 887 563
Tel: Angela - 0418717154
Email: angela@mckgroup.com.au

FOR:

2X 275/70R22.5
Odometer: 130,274 Kms
Model: Isuzu FTR
Reg No: 161TOS
Fleet No: MCK40

Description	Qty.	Unit Price	GST	Amount
GR27570225 - GOODRIDE 275/70R22.5 CR976A 16PR 148/145M ALL L/HAUL	2.0	\$385.00	\$70.00	\$770.00
WHBAL-TRS - Wheel Balance -Truck/Bus - Steel Rim Wheel Balance -Truck/Bus - Steel Rim	2.0	\$33.00	\$6.00	\$66.00
TYREDISPOSAL-TB - Tyre Disposal - Truck Bus Tyre Disposal - Truck / Bus	2.0	\$27.50	\$5.00	\$55.00

Supply strip and fit new tyres to pos 1,2
Rotate pos 1,2 to pos 3,4
All wheels tensioned

Subtotal	\$810.00
GST	\$81.00
Total	\$891.00
Paid	\$0.00
Balance Due	\$891.00

Direct Deposit

BSB: 014309
ACC: 433109765

Please use your invoice number as your payment reference when paying via Direct deposit/bank transfer. Thank-you for your business.

The Tyre Product Stewardship Scheme is a government supported scheme focused on responsible tyre disposal, and the sustainable management of end-of-life tyres. We have been an active member of the scheme since January 2023. Together, we aim to change the way end-of-life tyres are managed and make our industry more environmentally sustainable.



BRENDAN MCKENNA
EARTHMOVING
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill QLD 14037
ABN 35 108 043 312

SERVICE REPORT No. S 3181

Day: Friday Date: 16/02/2024

MCKENNA GROUP
PTY LTD

Vehicle/Trailer: Isuzu	Rego: 161-TOS	MCK Unit No. Mck40	Klms: 129,300km	Hours: N/A
------------------------	---------------	--------------------	-----------------	------------

☒ A SERVICE CHECKLIST

☒ TRUCK (Approx 10,000km - 12,000km)	☒	☒
Check Fault/Repair Log and carry out necessary repairs.	☒	Check brake system for leaks (service and main).
Grease all lubrication points.	☒	Drain condensation from air tanks.
Lift cab/pinion, urease pivots, check condition and tension of belts.	☒	Check steering joints and linkages.
Check power steering for fluid levels and leaks.	☒	Inspect for any obvious faults in suspension, structure or bodywork.
Check/top up engine oil and coolant level.	☒	Visual check of airbag suspension where fitted.
Check transmission and differential for fluid levels and leaks.	☒	Inspect wheel nuts and wheels for security, tyre tread and inflation.
Check drive/line and universal joints.	☒	Check number plates, all labels for due date condition and security.
Check all lights and reflectors.	☒	Check for visible exhaust emissions and lack of engine power.
Check horn, instruments, gauges, wipers and washers.	☒	Fault #/s Rectified (if Applicable)
Check battery terminals and security.	☒	
Inspect brake lining wear/travel and adjust if required.	☒	

☐ TRAILER (Approx 6 monthly/annually)

Grease all lubrication points.		Inspect for any obvious faults in suspension, structure or bodywork.
Inspect brake lining wear/travel and adjust if required.		Visual check of airbag suspension where fitted.
Check all lights and reflectors.		Check number plate, and all labels due date, condition and security.
Check condition of air lines and electrical cable.		Re-torque all "U" bolts and cross members.
Inspect wheel nuts and wheels for security, tyre tread and inflation.		Fault #/s Rectified (if Applicable)
Change oil in oil filled wheel bearings and check other wheel bearings.		

Notes:

Replace gearbox due to jumping out of 5th and couldn't get 6th. Fit new gearbox from Just Wrecking Isuzu

☒ B SERVICE CHECKLIST Including Items from Checklist A

☒ TRUCK (Approx 20,000km)	☒	☒
All components of "A" Service.	☒	Check wear/movement in pinion arm, drag arm, tie rods and spring shackles.
Change engine oil and filters.	☒	Replace or clean air cleaner as required.
Change fuel filters and bleed and check for leaks.	☒	Check trailer breakaway and mast system.
Test coolant and change water filters if required.	☒	
Check battery electrolyte level, terminals and security.	☒	Fault #/s Rectified (if Applicable)
Check clutch linkage, clutch brake operation and adjustment.	☒	
Check front steering hub all level.	☒	

☐ C SERVICE CHECKLIST Including Items from Checklist A and B

☐ TRUCK (Approx 200,000kms or annually)		
All components of "A" and "B" Service.		Change PTO Hydraulic filters.
Change power steering oil and filter.		Service air divers where applicable.
Change transmission oil and filter (300,000km for Synthetic Oil).		Re-torque all "U" bolts and cross members.
Change differential oil and filter.		Fault #/s Rectified (if Applicable)
Change oil in oil filled wheel bearings and check other wheel bearings.		
Check clutch linkage, clutch brake operation and adjustment.		

The person completing the service is to print their name and sign.

Name: Andrew Brandt
Signature: A Brandt

Date: 16/02/2024

OFFICE USE ONLY: Entered By: Amanda Smith

Name: Amanda Smith
Signature: Amanda Smith

Date: 16/02/2024

Heavy Vehicle Inspection Checklist

This checklist is used to complete a vehicle inspection that meets maintenance management standard 4 criteria(4). The inspection must be completed or supervised by a suitably qualified person whose name and signature must appear on the form.

Registration #	161-TOS	Owner's Details	
Reason for Inspection	Annual Inspection	Inspection location	Red Road,
Inspection Date	28/04/2023	Make	Isuzu
Inspection Time	12pm	Model	FTR
Odometer	115,697km	VIN #	JALFTR34LE7000008
Registration Expiry Date	20/11/2023	Vehicle Colour	White

Cross out those items not applicable.

Tick for Pass Cross for Fail

Item	Pass	N/a	Fail
Identification			
1 Registration Plates Affixed and Legible	☒	☐	☐
2 Compliance Plate Affixed	☒	☐	☐
Lights / Electrical			
3 Park / Tail / Number Plate / Clearance	☒	☐	☐
4 Head Lights / Auxiliary Lights	☒	☐	☐
5 Brake Lights	☒	☐	☐
6 Reflectors / Lenses	☒	☐	☐
7 Warning Device / Turning Indicators	☒	☐	☐
8 Wipers / Washers	☒	☐	☐
Glazing			
9 Material / Visibility	☒	☐	☐
10 Window Operation	☒	☐	☐
Seats / Seat Belts			
11 Mountings / Construction	☒	☐	☐
12 Fitting / Operation / Condition	☒	☐	☐
Wheels & Tyres			
13 Wheels / Security	☒	☐	☐
14 Wheel Bearings	☒	☐	☐
15 Tyres Tread Depth & Condition	☒	☐	☐
Body / Fittings/ Protrusions			
16 Corrosion / Security / Damage	☒	☐	☐
17 Door / Bonnet / Catches	☒	☐	☐
18 Rear Vision Mirrors	☒	☐	☐
19 Rear Marker Plates	☒	☐	☐
20 Body Fittings / Bumper Bars	☒	☐	☐
Tow Couplings			
21 Auto Tow Couplings	☒	☐	☐
22 King Pin / Skid Plate	☐	☒	☐
23 Tow Eye / Drawbar / Safety Chains	☐	☒	☐
24 Ball Race Turn Table	☐	☒	☐
25 Goose Neck	☐	☒	☐

Tick for Pass Cross for Fail

Item	Pass	N/a	Fail
Braking			
26 Brake Components	☒	☐	☐
27 Brake Operation(Refer Notes)	☒	☐	☐
Steering			
28 Steering Box / Pitman Arm	☒	☐	☐
29 Arms / Linkages / Wheel	☒	☐	☐
30 King Pins	☒	☐	☐
31 Free Play	☒	☐	☐
Suspension			
32 Springs	☒	☐	☐
33 Hangers / Pins / Bushes	☒	☐	☐
34 Air Bags / Air Suspension	☐	☒	☐
35 Shock Absorbers	☒	☐	☐
36 Axles / Cross Members	☒	☐	☐
Oil / Fuel Leaks			
37 Engine / Driveline	☒	☐	☐
38 Steering / Accessories	☒	☐	☐
Exhaust			
39 Leaks / Design / Security	☒	☐	☐
40 Emissions	☒	☐	☐
Mountings			
41 Engine / Transmission	☒	☐	☐
42 Body	☒	☐	☐
Air Systems			
43 Leaks / Low Air Warning / Contamination	☒	☐	☐
44 Breakaway Protection	☒	☐	☐
Under body / Chassis			
45 Cracks / Security	☒	☐	☐
46 Corrosion	☒	☐	☐
Mudguards / Mud Flaps			
47 Fitted as Required	☒	☐	☐

Notes:

1. If manufacture specifications are unknown refer to the Heavy Vehicle Inspection Manual for minimum requirements.
2. For a heavy vehicle built after 1930, the service brake must bring the vehicle or combination to a stop within 16.5m from a speed of 35km/h.
3. Trailer breakaway protection must be checked for operation.

Name: Andrew Brandt

Signature: A Brandt



BRENDAN MCKENNA
EARTHMOVING
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

SERVICE REPORT No. S 3144

Day: Friday Date: 28/04/2023

MCKENNA GROUP
PTY LTD

Vehicle/Trailer: Isuzu	Rego: 161-TOS	MCK Unit No. Mck40	Klms: 115.697km	Hours: N/A
------------------------	---------------	--------------------	-----------------	------------

☐ A SERVICE CHECKLIST

☐ TRUCK (Approx 10,000km - 12,000km)	☒
Check Fault Repair Log and carry out necessary repairs.	
Grease all lubrication points.	
Lift cab/body, grease pivots, check condition and tension of belts.	
Check power steering for fluid levels and leaks.	
Check top up engine oil and coolant level.	
Check transmission and differential for fluid levels and leaks.	
Check drive/line and universal joints.	
Check all lights and reflectors.	
Check horn, instruments, gauges, wipers and washers.	
Check battery terminals and security.	
Inspect brake lining wear/level and adjust if required.	

☐ TRAILER (Approx 6 monthly/annually)

Grease all lubrication points.	
Inspect brake lining wear/level and adjust if required.	
Check all lights and reflectors.	
Check condition of air lines and electrical cable.	
Inspect wheel nuts and wheels for security.	
Check for tread and inflation.	
Change oil in oil filled wheel bearings and check other wheel bearings.	

Notes:

☐ B SERVICE CHECKLIST Including Items from Checklist A

☐ TRUCK (Approx 20,000km)	☒
All components of "A" Service.	Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.
Change engine oil and filters.	Replace or clean air cleaner as required.
Change fuel filters and bleed and check for leaks.	Check trailer breakaway and mast system.
Test coolant and change water filters if required.	
Check battery electrolyte level, terminals and security.	Fault #/s Rectified (If Applicable)
Check clutch linkage, clutch brake operation and adjustment.	
Check front steering hub oil level.	

☒ C SERVICE CHECKLIST Including Items from Checklist A and B

☒ TRUCK (Approx 200,000kms or annually)	
All components of "A" and "B" Services.	Change PTO hydraulic filters.
Change power steering oil and filter.	Service air dryer where applicable.
Change transmission oil and filter (300,000km for Synthetic Oil).	Retorque all "U" bolts and cross members.
Change differential oil and filter.	Fault #/s Rectified (If Applicable)
Change oil in oil filled wheel bearings and check other wheel bearings.	
Check clutch linkage, clutch brake operation and adjustment.	

The person completing the service is to print their name and sign.

Name: Andrew Brandt

Signature: A Brandt

Date: 28/04/2023

OFFICE USE ONLY Entered By:

Name: Amanda Smith

Signature: A Smith

Date: 22.5.23

Heavy Vehicle Inspection Checklist

This checklist is used to complete a vehicle inspection that meets maintenance management standard 4 criteria(4). The inspection must be completed or supervised by a suitably qualified person whose name and signature must appear on the form.

Registration # 161TOS
Reason for Inspection Annual
Inspection Date 29/04/2022
Inspection Time 1pm
Odometer 102490
Registration Expiry Date 20-05-22

Owner's Details
Inspection location Red Road, Beerburrum
Make Isuzu
Model FTR
VIN # JALFTR34LE7000008
Vehicle Colour White

Cross out those items not applicable.

Tick for Pass Cross for Fail

Tick for Pass Cross for Fail

Item	Pass	N/a	Fail
Identification			
1 Registration Plates Affixed and Legible	☒	☐	☐
2 Compliance Plate Affixed	☒	☐	☐
Lights / Electrical			
3 Park / Tail / Number Plate / Clearance	☒	☐	☐
4 Head Lights / Auxiliary Lights	☒	☐	☐
5 Brake Lights	☒	☐	☐
6 Reflectors / Lenses	☒	☐	☐
7 Warning Device / Turning Indicators	☒	☐	☐
8 Wipers / Washers	☒	☐	☐
Glazing			
9 Material / Visibility	☒	☐	☐
10 Window Operation	☒	☐	☐
Seats / Seat Belts			
11 Mountings / Construction	☒	☐	☐
12 Fitting / Operation / Condition	☒	☐	☐
Wheels & Tyres			
13 Wheels / Security	☒	☐	☐
14 Wheel Bearings	☒	☐	☐
15 Tyres Tread Depth & Condition	☒	☐	☐
Body / Fittings/ Protrusions			
16 Corrosion / Security / Damage	☒	☐	☐
17 Door / Bonnet / Catches	☒	☐	☐
18 Rear Vision Mirrors	☒	☐	☐
19 Rear Marker Plates	☒	☐	☐
20 Body Fittings / Bumper Bars	☒	☐	☐
Tow Couplings			
21 Auto Tow Couplings	☒	☐	☐
22 King Pin / Skid Plate	☐	☒	☐
23 Tow Eye / Drawbar / Safety Chains	☐	☒	☐
24 Ball Race Turn Table	☐	☒	☐
25 Goose Neck	☐	☒	☐

Item	Pass	N/a	Fail
Braking			
26 Brake Components	☒	☐	☐
27 Brake Operation(Refer Notes)	☒	☐	☐
Steering			
28 Steering Box / Pitman Arm	☒	☐	☐
29 Arms / Linkages / Wheel	☒	☐	☐
30 King Pins	☒	☐	☐
31 Free Play	☒	☐	☐
Suspension			
32 Springs	☒	☐	☐
33 Hangers / Pins / Bushes	☒	☐	☐
34 Air Bags / Air Suspension	☒	☒	☐
35 Shock Absorbers	☒	☐	☐
36 Axles / Cross Members	☒	☐	☐
Oil / Fuel Leaks			
37 Engine / Driveline	☒	☐	☐
38 Steering / Accessories	☒	☐	☐
Exhaust			
39 Leaks / Design / Security	☒	☐	☐
40 Emissions	☒	☐	☐
Mountings			
41 Engine / Transmission	☒	☐	☐
42 Body	☒	☐	☐
Air Systems			
43 Leaks / Low Air Warning / Contamination	☒	☐	☐
44 Breakaway Protection	☒	☐	☐
Under body / Chassis			
45 Cracks / Security	☒	☐	☐
46 Corrosion	☒	☐	☐
Mudguards / Mud Flaps			
47 Fitted as Required	☒	☐	☐

Notes:

1. If manufacture specifications are unknown refer to the Heavy Vehicle Inspection Manual for minimum requirements.
2. For a heavy vehicle built after 1930, the service brake must bring the vehicle or combination to a stop within 16.5m from a speed of 35km/h.
3. Trailer breakaway protection must be checked for operation.

Name: Andrew Brandt

Signature: ABrandt



**BRENDAN MCKENNA
EARTHMOVING**
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

MCKENNA GROUP
PTY LTD

11 Montego Court
Eatons Hill | QLD 14037
ABN 35 108 043 312

SERVICE REPORT No. S 3078

Day: Friday Date: 20/05/2022

Vehicle/Trailer: Isuzu FRR	Rego: 161TOS	MCK Unit No. MCK40	Kilms: 103750	Hours: N/A
----------------------------	--------------	--------------------	---------------	------------

☒ A SERVICE CHECKLIST

☒ TRUCK (Approx 10,000km - 12,000km)	☒
Check Fault Repair Log and carry out necessary repairs.	☒
Grease all lubrication points.	☒
Lift cab/hopnet, grease pivots, check condition and tension of belt.	☒
Check power steering for fluid levels and leaks.	☒
Check/top up engine oil and coolant level.	☒
Check transmission and differential for fluid levels and leaks.	☒
Check drive/line and universal joints.	☒
Check all lights and reflectors.	☒
Check horn, instruments, gauges, wipers and washers.	☒
Check battery terminals and security.	☒
Inspect brake lining wear/travel and adjust if required.	☒

☐ TRAILER (Approx 6 monthly/annually)

Grease all lubrication points.	
Inspect brake lining wear/travel and adjust if required.	
Check all lights and reflectors.	
Check condition of air lines and electrical cable.	
Inspect wheel nuts and wheels for security, tyres for tread and inflation.	
Change oil in oil filled wheel bearings and check other wheel bearings.	

Notes:

Fit new drums brake linings and hub seals to 2nd drive axle. Adjust wheel bearings and brakes

☒ B SERVICE CHECKLIST Including items from Checklist A

☒ TRUCK (Approx 20,000km)	☒
All components of "A" Service.	Check wear/movement in pinion arm, drag arm, tie rods and spring shackles
Change engine oil and filters.	Replace or clean air cleaner as required.
Change fuel filters and bleed and check for leaks.	Check tailer breakaway and mast system.
Test coolant and change water filters if required.	
Check battery electrolyte level, terminals and security.	Fault #/s Rectified (if Applicable)
Check clutch linkage, clutch brake operation and adjustment.	
Check front steering hub oil level.	

☒ C SERVICE CHECKLIST Including items from Checklist A and B

☒ TRUCK (Approx 200,000kms or annually)	
All components of "A" and "B" Services.	Change PTO Hydraulic filters.
Change power steering oil and filter.	Service air dryers where applicable.
Change transmission oil and filter (900 cc/ltr for Synthetic Oil).	Re-torque all "U" bolts and cross members.
Change differential oil and filter.	Fault #/s Rectified (if Applicable)
Change oil in oil filled wheel bearings and check other wheel bearings.	
Check clutch linkage, clutch brake operation and adjustment.	

The person completing the service is to print their name and sign.

Name: Andrew Brandt

Signature: *A Brandt*

Date: 11/08/2022

OFFICE USE ONLY Entered By:

Name:

Amanda Smith

Signature:

Date: 26/5/22



BRENDAN MCKENNA
EARTHMOVING
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

SERVICE REPORT No. S 3056

Day: Saturday Date: 16/10/2021

MCKENNA GROUP
PTY LTD

Vehicle/Trailer: Isuzu	Rego: 161-TOS	MCK Unit No. MCK40	Klms: 96,615km	Hours: N/A
------------------------	---------------	--------------------	----------------	------------

☐ A SERVICE CHECKLIST

☒ TRUCK (Approx 10,000km - 12,000km) ✓

Check Fault Repair Log and carry out necessary repairs.	Check brake system for leaks (service and max).
Grease all lubrication points.	Drain condensation from air tanks.
Lift cab/hornet, grease pivots, check condition and tension of belts.	Check steering joints and linkages.
Check power steering for fluid levels and leaks.	Inspect for any obvious faults in suspension, structure or bodywork.
Check/rop up engine oil and coolant level.	Visual check of airbag suspension where fitted.
Check transmission and differential for fluid levels and leaks.	Inspect wheel nuts and wheels for security, tyres for tread and inflation.
Check chockles and universal joints.	Check number plates, all labels for due date condition and security.
Check all lights and reflectors.	Check for visible exhaust emissions and lack of engine power.
Check horn, instruments, gauges, wipers and washers.	Fault #/s Rectified (if Applicable)
Check battery terminals and security.	
Inspect brake lining wear/travel and adjust if required.	

☐ TRAILER (Approx 6 monthly/annually)

Grease all lubrication points.	Inspect for any obvious faults in suspension, structure or bodywork.
Inspect brake lining wear/travel and adjust if required.	Visual check of airbag suspension where fitted.
Check all lights and reflectors.	Check number plate, and all labels due date, condition and security.
Check condition of air lines and electrical cable.	Re-torque all "U" bolts and cross members.
Inspect wheel nuts and wheels for security, tyres for tread and inflation.	Fault #/s Rectified (if Applicable)
Change oil in oil filled wheel bearings and check other wheel bearings.	

Notes:

Diagnose air leak when park brake released, fit new park brake relay. Make sure air builds up and no air leak

☐ B SERVICE CHECKLIST Including Items from Checklist A

☒ TRUCK (Approx 20,000km) ✓

All components of "A" Service.	Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.
Change engine oil and filter.	Replace or clean air cleaner as required.
Change fuel filters and bleed and check for leaks.	Check trailer breakaway and mass system.
Test coolant and change water filters if required.	
Check battery electrolyte level, terminals and security.	Fault #/s Rectified (if Applicable)
Check clutch linkages, clutch brake operation and adjustment.	
Check front steering hub oil level.	

☐ C SERVICE CHECKLIST Including Items from Checklist A and B

☒ TRUCK (Approx 200,000kms or annually)

All components of "A" and "B" Services.	Change PTO Hydraulic filters.
Change power steering oil and filter.	Service air dryers where applicable.
Change transmission oil and filter (300,000km for Synthetic Oil).	Re-torque all "U" bolts and cross members.
Change differential oil and filter.	Fault #/s Rectified (if Applicable)
Change oil in oil filled wheel bearings and check other wheel bearings.	
Check clutch linkages, clutch brake operation and adjustment.	

The person completing the service is to print their name and sign.

Name: Andrew Brandt

Signature: *Andrew Brandt*

Date: 16/10/2021

OFFICE USE ONLY Entered By:

Name: *Angela McKenna*

Signature: *Angela McKenna*

Date: 21/10/21



**BRENDAN MCKENNA
EARTHMOVING**
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill QLD 4037
ABN 35 108 043 312

SERVICE REPORT No. S 3044

Day: Tuesday Date: 28/09/2021

**MCKENNA GROUP
PTY LTD**

Vehicle/Trailer: Isuzu	Rego: 161-TOS	MCK Unit No. MCK40	Klms: 96,396km	Hours:
------------------------	---------------	--------------------	----------------	--------

☐ A SERVICE CHECKLIST

☒ TRUCK (Approx 10,000km - 12,000km) ✓

Check Fault Repair Log and carry out necessary repairs.	Check brake system for leaks (service and max).
Grease all lubrication points.	Drain condensation from air tanks.
Lift cab/chassis, grease pivots, check condition and tension of belts.	Check steering joints and linkages.
Check power steering for fluid levels and leaks.	Inspect for any obvious faults in suspension, structure or bodywork.
Check/rop up engine oil and coolant level.	Visual check of airbag suspension where fitted.
Check transmission and differential for fluid levels and leaks.	Inspect wheel nuts and wheels for security.
Check driveline and universal joints.	Tires for tread and inflation.
Check all lights and reflectors.	Check number plates, all labels for due date condition and security.
Check horn, instruments, gauges, wipers and washers.	Check for visible exhaust emissions and lack of engine power.
Check battery terminals and security.	Fault #/s Rectified (if Applicable)
Inspect brake lining wear/travel and adjust if required.	

☐ TRAILER (Approx 6 monthly/annually)

Grease all lubrication points.	Inspect for any obvious faults in suspension, structure or bodywork.
Inspect brake lining wear/travel and adjust if required.	Visual check of airbag suspension where fitted.
Check all lights and reflectors.	Check number plate, and all labels due date, condition and security.
Check condition of air lines and electrical cable.	Re-torque all "U" bolts and cross members.
Inspect wheel nuts and wheels for security.	Fault #/s Rectified (if Applicable)
Tires for tread and inflation.	
Change oil in oil filled wheel bearings and check other wheel bearings.	

Notes:

☐ B SERVICE CHECKLIST Including items from Checklist A

☒ TRUCK (Approx 20,000km) ✓

All components of "A" Service.	Check wear/movement in piston arm, drag arm, tie rods and spring shackles.
Change engine oil and filters.	Replace or clean air cleaner as required.
Change fuel filters and bleed and check for leaks.	Check trailer breakaway and maxi system.
Test coolant and change water filters if required.	
Check battery electrolyte level, terminals and security.	Fault #/s Rectified (if Applicable)
Check clutch linkage, clutch brake operation and adjustment.	
Check front steering hub oil level.	

☒ C SERVICE CHECKLIST Including items from Checklist A and B

☒ TRUCK (Approx 200,000kms or annually)

All components of "A" and "B" Services.	✓	Change PTO hydraulic filters.	✓
Change power steering oil and filter.	✓	Service air dryers where applicable.	✓
Change transmission oil and filter (200,000kms for Synthetic Oil).	✓	Re-torque all "U" bolts and cross members.	✓
Change differential oil and filter.	✓	Fault #/s Rectified (if Applicable)	
Change oil in oil filled wheel bearings and check other wheel bearings.	✓		
Check clutch linkage, clutch brake operation and adjustment.	✓		

The person completing the service is to print their name and sign.

Name: Andrew Brindt

Signature: *Andrew Brindt*

Date: 28/09/2021

OFFICE USE ONLY Entered By:
Name: *Angela McEwen*

Signature: *Angela McEwen*

Date: 11/10/21

Heavy Vehicle Inspection Checklist

This checklist is used to complete a vehicle inspection that meets maintenance management standard 4 criteria(4). The inspection must be completed or supervised by a suitably qualified person whose name and signature must appear on the form.

Registration # 161-TOS
Reason for Inspection Annual Inspection
Inspection Date 29/04/2021
Inspection Time 8am
Odometer 92575Km
Registration Expiry Date 20/11/2021

Owner's Details
Inspection location Delaney's Creek
Make Isuzu
Model FTR900
VIN # JALFTR34LE7000008
Vehicle Colour White

Cross out those items not applicable.

Tick for Pass Cross for Fail

Item	Pass	N/a	Fail
Identification			
1 Registration Plates Affixed and Legible	☒	☐	☐
2 Compliance Plate Affixed	☒	☐	☐
Lights / Electrical			
3 Park / Tail / Number Plate / Clearance	☒	☐	☐
4 Head Lights / Auxiliary Lights	☒	☐	☐
5 Brake Lights	☒	☐	☐
6 Reflectors / Lenses	☒	☐	☐
7 Warning Device / Turning Indicators	☒	☐	☐
8 Wipers / Washers	☒	☐	☐
Glazing			
9 Material / Visibility	☒	☐	☐
10 Window Operation	☒	☐	☐
Seats / Seat Belts			
11 Mountings / Construction	☒	☐	☐
12 Fitting / Operation / Condition	☒	☐	☐
Wheels & Tyres			
13 Wheels / Security	☒	☐	☐
14 Wheel Bearings	☒	☐	☐
15 Tyres Tread Depth & Condition	☒	☐	☐
Body / Fittings/ Protrusions			
16 Corrosion / Security / Damage	☒	☐	☐
17 Door / Bonnet / Catches	☒	☐	☐
18 Rear Vision Mirrors	☒	☐	☐
19 Rear Marker Plates	☒	☐	☐
20 Body Fittings / Bumper Bars	☒	☐	☐
Tow Couplings			
21 Auto Tow Couplings	☒	☐	☐
22 King Pin / Skid Plate	☐	☒	☐
23 Tow Eye / Drawbar / Safety Chains	☐	☒	☐
24 Ball Race Turn Table	☐	☒	☐
25 Goose Neck	☐	☒	☐

Tick for Pass Cross for Fail

Item	Pass	N/a	Fail
Braking			
26 Brake Components	☒	☐	☐
27 Brake Operation (Refer Notes)	☒	☐	☐
Steering			
28 Steering Box / Pitman Arm	☒	☐	☐
29 Arms / Linkages / Wheel	☒	☐	☐
30 King Pins	☒	☐	☐
31 Free Play	☒	☐	☐
Suspension			
32 Springs	☒	☐	☐
33 Hangers / Pins / Bushes	☒	☐	☐
34 Air Bags / Air Suspension	☐	☒	☐
35 Shock Absorbers	☒	☐	☐
36 Axles / Cross Members	☒	☐	☐
Oil / Fuel Leaks			
37 Engine / Driveline	☒	☐	☐
38 Steering / Accessories	☒	☐	☐
Exhaust			
39 Leaks / Design / Security	☒	☐	☐
40 Emissions	☒	☐	☐
Mountings			
41 Engine / Transmission	☒	☐	☐
42 Body	☒	☐	☐
Air Systems			
43 Leaks / Low Air Warning / Contamination	☒	☐	☐
44 Breakaway Protection	☒	☐	☐
Under body / Chassis			
45 Cracks / Security	☒	☐	☐
46 Corrosion	☒	☐	☐
Mudguards / Mud Flaps			
47 Fitted as Required	☒	☐	☐

Notes:

1. If manufacture specifications are unknown refer to the Heavy Vehicle Inspection Manual for minimum requirements.
2. For a heavy vehicle built after 1930, the service brake must bring the vehicle or combination to a stop within 16.5m from a speed of 35km/h.
3. Trailer breakaway protection must be checked for operation.

Name: Andrew Brandt

Signature: A Brandt



Tax Invoice

Invoice #: 00047681

PO Box 551
Bribie Island Qld 4507

Ph 07 5499 1049
Fax 07 5499 3643
Email sales@timstyresandauto.com.au

A.B.N. 82 505 142 194

Ship To: Brendan McKenna
Earthmoving Pty-Ltd
11 Montego Court
Eatons hill QLD 4037

Bill To:

**Brendan McKenna
Earthmoving Pty-Ltd
11 Montego Court
Eatons hill QLD 4037**



Vehicle Type / Rego		Odometer	Order No	TERMS	DATE	
Isuzu MCK40		82175;	161TOS	Net 30th after EOM	1/10/2020	
QTY	ITEM	DESCRIPTION	Price Per	UNIT	Total Price Exc GST	Tax Code
2	TE27570225	To supply strip and fit - Techking 275/70R22.5 TKST 18pl to positio 5 6	\$318.18		\$636.36	G S T
1	Disptr	Tyre Disposal Truck	\$15.00		\$15.00	G S T
1	SERdoc	Service Docket - 50219 1-10-2020				G S T
				SALE AMT.	\$651.36	
Preferred payment is by direct deposit to Westpac BSB 034119 Account 172104. Please quote your business name and/or invoice number for ease of allocation. (creditor) watch				GST	\$65.14	
				TOTAL AMT.	\$716.50	
				PAID TODAY	\$0.00	
<u>Note our payment terms are strictly 30 days from end of month.</u>				BALANCE DUE	\$716.50	



**BRENDAN MCKENNA
EARTHMOVING**
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill QLD 4037
ABN 35 108 043 312

SERVICE REPORT No. S 3032

Day: Friday Date: 25/09/2020

MCKENNA GROUP
PTY LTD

Vehicle/Trailer: Iuzu Tipper	Rego: 16TOS	MCK Unit No. MCK40	Klms: 81425	Hours: -
------------------------------	-------------	--------------------	-------------	----------

☐ A SERVICE CHECKLIST

☐ TRUCK (Approx 10,000km - 12,000km)	☒
Check Fault Repair Log and carry out necessary repairs.	☒
Grease all lubrication points.	☒
Lift cab/hornet, grease photo, check condition and tension of belts.	☒
Check power steering for fluid levels and leaks.	☒
Check top up engine oil and coolant level.	☒
Check transmission and differential for fluid levels and leaks.	☒
Check oilline and universal joints.	☒
Check all lights and reflectors.	☒
Check horn, instruments, gauges, wipers and washers.	☒
Check battery terminals and security.	☒
Inspect brake lining wear/travel and adjust if required.	☒

☐ TRAILER (Approx 6 monthly/annually)

Grease all lubrication points.	
Inspect brake lining wear/travel and adjust if required.	
Check all lights and reflectors.	
Check condition of air lines and electrical cable.	
Inspect wheel nuts and wheels for security, tyre for tread and inflation.	
Change oil in oil filled wheel bearings and check other wheel bearings.	

Notes:

☐ B SERVICE CHECKLIST Including Items from Checklist A

☐ TRUCK (Approx 20,000km)	☒
All components of "A" Service.	☒
Change engine oil and filters.	☒
Change fuel filters and bleed and check for leaks.	☒
Test coolant and change water filters if required.	☒
Check battery electrolyte level, terminals and security.	☒
Check clutch linkage, clutch brake operation and adjustment.	☒
Check front steering hub oil level.	☒
Check wear/movement in pinion arm, drag arm, tie rods and spring shackles.	☒
Replace or clean air cleaner as required.	☒
Check trailer breakaway and reset system.	☒
Fault #/s Rectified (If Applicable)	

☒ C SERVICE CHECKLIST Including Items from Checklist A and B

☒ TRUCK (Approx 200,000kms or annually)

All components of "A" and "B" Service.	☒
Change power steering oil and filter.	☒
Change transmission oil and filter (approx 6000km for Synthetic Oil).	☒
Change differential oil and filter.	☒
Change oil in oil filled wheel bearings and check other wheel bearings.	☒
Check clutch linkage, clutch brake operation and adjustment.	☒
Change PTO Hydraulic filters.	☒
Service air dryer where applicable.	☒
Re-torque all "U" bolts and cross members.	☒
Fault #/s Rectified (If Applicable)	

The person completing the service is to print their name and sign.

Name: Matthew Harries

Signature: *Matthew Harries*

Date: 25/09/2020

OFFICE USE ONLY Entered By:

Name: Angela Wignall

Signature: *Angela Wignall*

Date: 24 Oct 20



MCKENNA GROUP
PTY LTD

BRENDAN MCKENNA
EARTHMOVING

MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

TRUCK & TRAILER ANNUAL INSPECTION

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

No. AS318

Day Tuesday

Date 05/05/2020

Registration Number	Make and Body Type:	Klms:	Unit No.:
161TOS	Isuzu Tipper	72506	MCK40

Note: Cross out whichever is not applicable

☐ OK

Satisfactory

☒ X

Defective

LIGHTING EQUIPMENT		SEAT BELTS		MOUNTINGS	
Battery Cradle/Security	OK	Fitted as required	OK	Engine	OK
Headlights/Auxiliary Lights	OK	Operation	OK	Transmission	OK
Park Lights	OK	Webbing/Fittings	OK	Body	OK
Tail Lights	OK	Anchorage	OK	STEERING	
Break Lights	OK	MUDGUARDS/MUDFLAPS		Free Play/Seals	OK
Reflectors/Marker Plates	OK	Fitted as Required	OK	Steering Box/Pitman Arm	OK
Clearance Lights	OK	Spray Suppression	OK	Arms/Linkages	OK
Number Plate Light	OK	SIDE & BODY PANELS		King Pins/Bushes	OK
Reversing Light	OK	Cracks/Security	OK	Steering Wheel	OK
TURN SIGNALS		Corrosion/Damage	OK	SUSPENSION	
Operation	OK	FITTINGS & PROTRUSIONS		Shock Absorbers	OK
Colour	OK	Corrosion/Damage	OK	Cross Members	OK
Visibility	OK	Door/Bonnet/Catches	OK	Axles	OK
WARNING DEVICE		Rear Vision Mirrors	OK	Springs/U Bolts	OK
Control	OK	Body Fittings/Bumper Bars	OK	Air Bags/Air Suspension	N/A
Audibility	OK	EXHAUST SYSTEM		Hangers/Pins/Bushes	OK
WIPERS/WASHERS		Leaks/Design/Security	OK	Bolts/Locknuts/Pins	OK
Blades/Insert	OK	Emission	OK	WHEELS & TYRES	
Controls/Motor	OK	UNDER BODY & CHASSIS		Wheels/Security	OK
GLAZING		Cracks/Security/Corrosion	OK	Tyres	OK
Material/Visibility	OK	OIL LEAKS		Wheel Bearings	OK
Window Operation	OK	Engine	OK	BRAKING SYSTEM	
SEATS		Transmission	OK	Service Brake	OK
Mounting/Construction	OK	Differential/s	OK	Park Brake	OK
Fitting/Operation	OK	Steering/Accessories	OK	TOW COUPLINGS	
Condition	OK	AIR SYSTEM		King Pin/Skid Plate/Auto	N/A
SPEED LIMITER		Leaks/Contamination	OK	Turntable/Ringfeeder/Ball Race	OK
Speed Limiter operational and has not been tampered with	OK	Breakaway/Protection Valve	OK	Tow Eye/Draw Bar/Safety Chains	N/A

DETAILS OF ITEMS REJECTED

CERTIFICATION

I certify the above information is true and that the vehicle is in a safe and thoroughly serviceable condition

Mechanic's Name: Matthew Harries

Mechanic's Signature:

Date: 05/05/2020

OFFICE USE ONLY Entered By:

Name:

Angela McKenna

Signature:

Date:

8/5/20



BRENDAN MCKENNA
EARTHMOVING
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

SERVICE REPORT No. S 3007

Day: Friday Date: 21/02/2020

MCKENNA GROUP
PTY LTD

Vehicle/Trailer: Isuzu Tipper	Rego: 161TOS	MCK Unit No. MCK40	Kms: 70123	Hours: -
-------------------------------	--------------	--------------------	------------	----------

☒ A SERVICE CHECKLIST

☐ TRUCK (Approx 10,000km - 12,000km)	☒	☒
Check Fault Repair Log and carry out necessary repairs.	☒	Check brake system for leaks (service and max).
Grease all lubrication points.	☒	Drain condensation from air tanks.
Lift cab/hood, grease pivots, check condition and tension of belts.	☒	Check steering joints and linkages.
Check power steering for fluid levels and leaks.	☒	Inspect for any obvious faults in suspension, structure or bodywork.
Check/top up engine oil and coolant level.	☒	Visual check of airbag suspension where fitted.
Check transmission and differential for fluid levels and leaks.	☒	Inspect wheel nuts and wheels for security, tyres for tread and inflation.
Check driveline and universal joints.	☒	Check number plates, all labels for due date condition and security.
Check all lights and reflectors.	☒	Check for visible exhaust emissions and lack of engine power.
Check horn, instruments, gauges, wipers and washers.	☒	Fault #/s Rectified (if Applicable)
Check battery terminals and security.	☒	
Inspect brake lining wear/level and adjust if required.	☒	

☐ TRAILER (Approx 6 monthly/annually)

Grease all lubrication points.		Inspect for any obvious faults in suspension, structure or bodywork.
Inspect brake lining wear/level and adjust if required.		Visual check of airbag suspension where fitted.
Check all lights and reflectors.		Check number plates, and all labels due date, condition and security.
Check condition of air lines and electrical cable.		Re-torque all "U" bolts and cross members.
Inspect wheel nuts and wheels for security, tyres for tread and inflation.		Fault #/s Rectified (if Applicable)
Change oil in oil filled wheel bearings and check other wheel bearings.		

Notes:

☒ B SERVICE CHECKLIST Including items from Checklist A

☐ TRUCK (Approx 20,000km)	☒	☒
All components of "A" Service.		Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.
Change engine oil and filters.	☒	Replace or clean air cleaner as required.
Change fuel filters and bleed and check for leaks.	☒	Check trailer breakaway and mast system.
Test coolant and change water filters if required.	☒	
Check battery electrolyte level, terminals and security.	☒	Fault #/s Rectified (if Applicable)
Check clutch linkage, clutch brake operation and adjustment.	☒	
Check front steering hub oil level.	☒	

☒ C SERVICE CHECKLIST Including items from Checklist A and B

☒ TRUCK (Approx 200,000kms or annually)	☒	☒
All components of "A" and "B" Services.	☒	Change PTO Hydraulic filters.
Change power steering oil and filter.	☒	Service air dryers where applicable.
Change transmission oil and filter (300,000km for Synthetic Oil).	☒	Re-torque all "U" bolts and cross members.
Change differential oil and filter.	☒	Fault #/s Rectified (if Applicable)
Change oil in oil filled wheel bearings and check other wheel bearings.	☒	Drain valve on air tank leaking - Repaired
Check clutch linkage, clutch brake operation and adjustment.	☒	Nitto fitting on air tank leaking - Replaced

The person completing the service is to print their name and sign.

Name: Matthew Harries

Signature:

Date: 21/02/2020

OFFICE USE ONLY Entered By:
Name: A. McKenna

Signature:

Date: 03/03/20



Tax Invoice

Invoice #: 00045025

PO Box 551
Bribie Island Qld 4507



Ph 07 5499 1049
Fax 07 5499 3643
Email sales@timstyresandauto.com.au

A.B.N. 82 505 142 194

Ship To: **Brendan McKenna**
Earthmoving Pty-Ltd
11 Montego Court
Eatons hill QLD 4037

Bill To:

Brendan McKenna
Earthmoving Pty-Ltd
11 Montego Court
Eatons hill QLD 4037

Vehicle Type / Rego		Odometer	Order No	TERMS	DATE	
Isuzu 161TOS		67949;	161TOS	Net 30th after EOM	16/01/2020	
QTY	ITEM	DESCRIPTION	Price Per	UNIT	Total Price Exc GST	Tax Code
2	HM27570225ATT 101	Haulmax 275/70R22.5ATT101	\$326.00		\$652.00	G S T
2	TRWBAL	Wheel balance (truck) (Steel)	\$30.00		\$60.00	G S T
2	Disptr	Tyre Disposal Truck	\$15.00		\$30.00	G S T
1	TI17525TUL300	Tianli 17.5R25 TUL300	\$908.64		\$908.64	G S T
1	O Ring	O Ring	\$22.72		\$22.72	G S T
1	SERdoc	Service Docket - 47894 16-1-2020				G S T
					SALE AMT.	\$1,673.36
					GST	\$167.34
					TOTAL AMT.	\$1,840.70
					PAID TODAY	\$0.00
					BALANCE DUE	\$1,840.70

Preferred payment is by direct deposit to Westpac BSB 034119 Account 172104.
Please quote your business name and/or invoice number for ease of allocation.
(creditor) watch

Note our payment terms are strictly 30 days from end of month.



MCKENNA GROUP
PTY LTD

BRENDAN MCKENNA
EARTHMOVING

MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

TRUCK & TRAILER ANNUAL INSPECTION

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

No. AS 155

Day Wednesday
Date 1/5/19

Registration Number:	Make and Body Type:	Klms:	Unit No.:
161 TOS	Isuzu Tipper	58717	MCK40

Note: Cross out whichever is not applicable



Satisfactory



Defective

LIGHTING EQUIPMENT		SEAT BELTS		MOUNTINGS	
Battery Cradle/Security	☒	Fitted as required	☒	Engine	☒
Headlights/Auxiliary Lights	☒	Operation	☒	Transmission	☒
Park Lights	☒	Webbing/Fittings	☒	Body	☒
Tail Lights	☒	Anchorage	☒	STEERING	
Break Lights	☒	MUDGUARDS/MUDFLAPS		Free Play/Seals	☒
Reflectors/Marker Plates	☒	Fitted as Required	☒	Steering Box/Pitman Arm	☒
Clearance Lights	☒	Spray Suppression	☒	Arms/Linkages	☒
Number Plate Light	☒	SIDE & BODY PANELS		King Pins/Bushes	☒
Reversing Light	☒	Cracks/Security	☒	Steering Wheel	☒
TURN SIGNALS		Corrosion/Damage	☒	SUSPENSION	
Operation	☒	FITTINGS & PROTRUSIONS		Shock Absorbers	☒
Colour	☒	Corrosion/Damage	☒	Cross Members	☒
Visibility	☒	Door/Bonnet/Catches	☒	Axles	☒
WARNING DEVICE		Rear Vision Mirrors	☒	Springs/U Bolts	☒
Control	☒	Body Fittings/Bumper Bars	☒	Air Bags/Air Suspension	N/A
Audibility	☒	EXHAUST SYSTEM		Hangers/Pins/Bushes	☒
WIPERS/WASHERS		Leaks/Design/Security	☒	Bolts/Locknuts/Pins	☒
Blades/Insert	☒	Emission	☒	WHEELS & TYRES	
Controls/Motor	☒	UNDER BODY & CHASSIS		Wheels/Security	☒
GLAZING		Cracks/Security/Corrosion	☒	Tyres	☒
Material/Visibility	☒	OIL LEAKS		Wheel Bearings	☒
Window Operation	☒	Engine	☒	BRAKING SYSTEM	
SEATS		Transmission	☒	Service Brake	☒
Mounting/Construction	☒	Differential/s	☒	Park Brake	☒
Fitting/Operation	☒	Steering/Accessories	☒	TOW COUPLINGS	
Condition	☒	AIR SYSTEM		King Pin/Skid Plate/Auto	N/A
SPEED LIMITER		Leaks/Contamination	☒	Turntable/Ringfeeder/Ball Race	N/A
Speed Limiter operational and has not been tampered with	☒	Breakaway/Protection Valve	☒	Tow Eye/Draw Bar/Safety Chains	☒

DETAILS OF ITEMS REJECTED

CERTIFICATION

I certify the above information is true and that the vehicle is in a safe and thoroughly serviceable condition

Mechanic's Name: Brendan McKenna Mechanic's Signature: [Signature] Date: 1/5/19

OFFICE USE ONLY Entered By:
Name: A. McKenna Signature: [Signature] Date: 8/5/19



BRENDAN MCKENNA
EARTHMOVING
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

SERVICE REPORT No. S 2423

Day: Thursday Date: 21/03/19

MCKENNA GROUP
PTY LTD

Vehicle/Trailer: <u>Iswu Tipper</u>	Rego: <u>16/TOS</u>	MCK Unit No. <u>MCK40</u>	Klms: <u>57518</u>	Hours: <u>-</u>
-------------------------------------	---------------------	---------------------------	--------------------	-----------------

☒ A SERVICE CHECKLIST

☒ TRUCK (Approx 10,000km)

Check Fault Repair Log and carry out necessary repairs.	☒	Check brake system for leaks (service and maxi).	☒
Grease all lubrication points.	☒	Drain condensation from air tanks.	☒
Lift cab/bonnet, grease pivots, check condition and tension of belts.	☒	Check steering joints and linkages.	☒
Check power steering for fluid levels and leaks.	☒	Inspect for any obvious faults in suspension, structure or bodywork.	☒
Check/top up engine oil and coolant level.	☒	Visual check of airbag suspension where fitted.	☒
Check transmission and differential for fluid levels and leaks.	☒	Inspect wheel nuts and wheels for security, tyres for tread and inflation.	☒
Check driveline and universal joints.	☒	Check number plates, all labels for due date condition and security.	☒
Check all lights and reflectors.	☒	Check for visible exhaust emissions and lack of engine power.	☒
Check horn, instruments, gauges, wipers and washers.	☒	Fault #'s Rectified (If Applicable)	☒
Check battery terminals and security.	☒		
Inspect brake lining wear/travel and adjust if required.	☒		

☐ TRAILER (Approx 6 monthly/annually)

Grease all lubrication points.		Inspect for any obvious faults in suspension, structure or bodywork.	
Inspect brake lining wear/travel and adjust if required.		Visual check of airbag suspension where fitted.	
Check all lights and reflectors.		Check number plate, and all labels due date, condition and security.	
Check condition of air lines and electrical cable.		Re-torque all "U" bolts and cross members.	
Inspect wheel nuts and wheels for security, tyres for tread and inflation.		Fault #'s Rectified (If Applicable)	
Change oil in oil filled wheel bearings and check other wheel bearings.			

Notes: Needs a new retractable tarp soon as holes are getting bigger in mesh.

☐ B SERVICE CHECKLIST Including items from Checklist A

☐ TRUCK (Approx 20,000km)

All components of "A" Service.		Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.	☒
Change engine oil and filters.		Replace or clean air cleaner as required.	
Change fuel filters and bleed and check for leaks.		Check trailer breakaway and maxi system.	
Test coolant and change water filters if required.			
Check battery electrolyte level, terminals and security.		Fault #'s Rectified (If Applicable)	
Check clutch linkage, clutch brake operation and adjustment.			
Check front steering hub oil level.			

☐ C SERVICE CHECKLIST Including items from Checklist A and B

☐ TRUCK (Approx 200,000kms or annually)

All components of "A" and "B" Services.		Change PTO Hydraulic filters.	
Change power steering oil and filter.		Service air dryers where applicable.	
Change transmission oil and filter (300,000km for Synthetic Oil).		Re-torque all "U" bolts and cross members.	
Change differential oil and filter.		Fault #'s Rectified (If Applicable)	
Change oil in oil filled wheel bearings and check other wheel bearings.			
Check clutch linkage, clutch brake operation and adjustment.			

The person completing the service is to print their name and sign.

Name: Matthew Harris

Signature: [Signature]

Date: 21/03/19

OFFICE USE ONLY Entered By:

Name: Angela McKenna

Signature: [Signature]

Date: 26/3/19



McKENNA HAULAGE

TRUCK & TRAILER ANNUAL INSPECTION

No. AS 224

Day Saturday
Date 12 / 5 / 18

Registration Number:	Make and Body Type:	Klms:	Unit No.:
IGI TOS	ISUZU Tipper	44862	MCK40

Defective

LIGHTING EQUIPMENT		SEAT BELTS		MOUNTINGS	
Battery Cradle/Security	✓	Fitted as required	✓	Engine	✓
Headlights/Auxiliary Lights	✓	Operation	✓	Transmission	✓
Park Lights	✓	Webbing/Fittings	✓	Body	✓
Tail Lights	✓	Anchorage	✓	STEERING	
Break Lights	✓	MUDGUARDS/MUDFLAPS		Free Play/Seals	✓
Reflectors/Marker Plates	✓	Fitted as Required	✓	Steering Box/Pitman Arm	✓
Clearance Lights	✓	Spray Suppression	✓	Arms/Linkages	✓
Number Plate Light	✓	SIDE & BODY PANELS		King Pins/Bushes	✓
Reversing Light	✓	Cracks/Security	✓	Steering Wheel	✓
TURN SIGNALS		Corrosion/Damage	✓	SUSPENSION	
Operation	✓	FITTINGS & PROTRUSIONS		Shock Absorbers	✓
Colour	✓	Corrosion/Damage	✓	Cross Members	✓
Visibility	✓	Door/Bonnet/Catches	✓	Axles	✓
WARNING DEVICE		Rear Vision Mirrors	✓	Springs/U Bolts	✓
Control	✓	Body Fittings/Bumper Bars	✓	Air Bags/Air Suspension	✓
Audibility	✓	EXHAUST SYSTEM		Hangers/Pins/Bushes	✓
WIPERS/WASHERS		Leaks/Design/Security	✓	Bolts/Locknuts/Pins	✓
Blades/Insert	✓	Emission	✓	WHEELS & TYRES	
Controls/Motor	✓	UNDER BODY & CHASSIS		Wheels/Security	✓
GLAZING		Cracks/Security/Corrosion	✓	Tyres	✓
Material/Visibility	✓	OIL LEAKS		Wheel Bearings	✓
Window Operation	✓	Engine	✓	BRAKING SYSTEM	
SEATS		Transmission	✓	Service Brake	✓
Mounting/Construction	✓	Differential/s	✓	Park Brake	✓
Fitting/Operation	✓	Steering/Accessories	✓	TOW COUPLINGS	
Condition	✓	AIR SYSTEM		King Pin/Skid Plate/Auto	✓
SPEED LIMITER		Leaks/Contamination	✓	Turntable/Ringfeeder/Ball Race	✓
Speed Limiter operational and has not been tampered with	✓	Breakaway/Protection Valve	✓	Tow Eye/Draw Bar/Safety Chains	✓

DETAILS OF ITEMS REJECTED

CERTIFICATION

I certify the above information is true and that the vehicle is in a safe and thoroughly serviceable condition

Mechanic's Name: Brendan McKenna Mechanic's Signature: [Signature] Date: 12/5/18

OFFICE USE ONLY Entered By: Angela McKenna Name: Angela McKenna Signature: [Signature] Date: 12/5/18



BRENDAN MCKENNA
EARTHMOVING
MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

SERVICE REPORT No. S 2261
Day: **FRIDAY** Date: **4 / 05 / 18**

MCKENNA GROUP
PTY LTD

Vehicle/Trailer: ISUZU	Rego: 161TOS	MCK Unit No. MCK40	Klms: 44573	Hours:
-------------------------------	---------------------	---------------------------	--------------------	--------

☐ **A SERVICE CHECKLIST**

☒ **TRUCK (Approx 10,000km)**

Check Fault Repair Log and carry out necessary repairs.	✓	Check brake system for leaks (service and max).	✓
Grease all lubrication points.	✓	Drain condensation from air tanks.	✓
Lift cab/bonnet, grease pivots, check condition and tension of belts.	✓	Check steering joints and linkages.	✓
Check power steering for fluid levels and leaks.	✓	Inspect for any obvious faults in suspension, structure or bodywork.	✓
Check/top up engine oil and coolant level.	✓	Visual check of airbag suspension where fitted.	N/A
Check transmission and differential for fluid levels and leaks.	✓	Inspect wheel nuts and wheels for security, tyres for tread and inflation.	✓
Check driveline and universal joints.	✓	Check number plates, all labels for due date condition and security.	✓
Check all lights and reflectors.	✓	Check for visible exhaust emissions and lack of engine power.	✓
Check horn, instruments, gauges, wipers and washers.	✓	Fault #/s Rectified (if Applicable)	
Check battery terminals and security.	✓		
Inspect brake lining wear/travel and adjust if required.	✓		

☐ **TRAILER (Approx 6 monthly/annually)**

Grease all lubrication points.		Inspect for any obvious faults in suspension, structure or bodywork.	
Inspect brake lining wear/travel and adjust if required.		Visual check of airbag suspension where fitted.	
Check all lights and reflectors.		Check number plate, and all labels due date, condition and security.	
Check condition of air lines and electrical cable.		Re-torque all "U" bolts and cross members.	
Inspect wheel nuts and wheels for security, tyres for tread and inflation.		Fault #/s Rectified (if Applicable)	
Change oil in oil filled wheel bearings and check other wheel bearings.			

Notes:

☐ **B SERVICE CHECKLIST** Including items from Checklist A

☒ **TRUCK (Approx 20,000km)**

All components of "A" Service.	✓	Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.	✓
Change engine oil and filters.	✓	Replace or clean air cleaner as required.	✓
Change fuel filters and bleed and check for leaks.	✓	Check trailer breakaway and max system.	✓
Test coolant and change water filters if required.	✓	Fault #/s Rectified (if Applicable)	
Check battery electrolyte level, terminals and security.	✓		
Check clutch linkage, clutch brake operation and adjustment.	✓		
Check front steering hub oil level.	✓		

☒ **C SERVICE CHECKLIST** Including items from Checklist A and B

☐ **TRUCK (Approx 200,000kms or annually)**

All components of "A" and "B" Services.	✓	Change PTO Hydraulic filters.	✓
Change power steering oil and filter.	✓	Service air dryers where applicable.	✓
Change transmission oil and filter (300,000km for Synthetic Oil).	✓	Re-torque all "U" bolts and cross members.	✓
Change differential oil and filter.	✓	Fault #/s Rectified (if Applicable)	
Change oil in oil filled wheel bearings and check other wheel bearings.	✓		
Check clutch linkage, clutch brake operation and adjustment.	✓		

The person completing the service is to print their name and sign.

Name: **Andrew A. Brundt** Date: **4 / 05 / 18**

Signature:

OFFICE USE ONLY Entered By: **Angela McKenna**
Name: **Angela McKenna** Date: **10 / 5 / 18**
Signature: **Angela McKenna**



McKENNA GROUP
PTY LTD

BRENDAN MCKENNA
EARTHMOVING

MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

SERVICE REPORT

No. S 2119

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

Day _____
Date 5/06/17

Machine:	<u>ISUZU</u>	Hours:	
Rego:	<u>161 TOS</u>	Klms:	<u>34534</u>
Plant:		Unit No.:	<u>MCK 40</u>

☒ A SERVICE CHECKLIST

Due : Weekly or ~~5,000 to 8,000kms~~ 10,000 kms

		NOTES	
Check Fault Repair Log and carry out necessary repairs.	☒	Inspect brake lining wear/travel and adjust if required.	☒
Grease all lubrication points.	☒	Check brake system for leaks (service and maxi).	☒
Lift cab/bonnet, grease pivots, check condition and tension of belts.	☒	Drain condensation from air tanks.	☒
Check power steering for fluid levels and leaks.	☒	Check steering joints and linkages.	☒
Check/top up engine oil and coolant level.	☒	Inspect for any obvious faults in suspension, structure or bodywork.	☒
Check transmission and differential for fluid levels and leaks.	☒	Visual check of airbag suspension where fitted.	☒
Check driveline and universal joints.	☒	Inspect wheel nuts and wheels for security, tyres for tread and inflation.	☒
Check all lights and reflectors.	☒	Check number plates, all labels for due date condition and security.	☒
Check horn, instruments, gauges, wipers and washers.	☒	Check for visible exhaust emissions and lack of engine power.	☒
Check battery terminals and security.	☒	Note numbers of fault repairs rectified -	<u>33277</u>

TRAILER

		NOTES	
Grease all lubrication points		Inspect for any obvious faults in suspension, structure or bodywork.	
Inspect brake lining wear/travel and adjust if required.		Visual check of airbag suspension where fitted.	
Check all lights and reflectors		Check number plate, and all labels due date, condition and security	
Check condition of air lines and electrical cable			
Inspect wheel nuts and wheels for security, tyres for tread and inflation		Note numbers of fault repairs rectified -	

☒ B SERVICE CHECKLIST Including items from Checklist A

TRUCK & TRAILER (Approx 20,000kms)

		NOTES	
All components of "A" Service.	☒	Check front steering hub oil level	☒
Change engine oil and filters.	☒	Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.	☒
Change fuel filters and bleed and check for leaks.	☒	Replace or clean air cleaner as required.	☒
Test coolant and change water filters if required	☒	Check trailer breakaway and maxi system	☒
Check battery electrolyte level, terminals and security	☒	Note numbers of fault repairs rectified -	☒
Check clutch linkage, clutch brake operation and adjustment	☒		

☐ C SERVICE CHECKLIST Including items from Checklist A and B

TRUCK & TRAILER (Approx 200,000kms or annually)

		NOTES	
All components of "A" and "B" Services.	☒	Change PTO Hydraulic filters.	☒
Change power steering oil and filter.	☒	Service air dryers where applicable.	☒
Change transmission oil and filter (300,000kms for Synthetic Oil).	☒	Re-torque all "U" bolts and cross members.	☒
Change differential oil and filter.	☒		
Change oil in oil filled wheel bearings and check other wheel bearings.	☒	Note numbers of fault repairs rectified -	

The person completing the service is to print their name and sign.

Name: ANDREW Signature: [Signature] Date: 5/06/17

OFFICE USE ONLY Entered By: JOS Signature: [Signature] Date: 23/1/18



MCKENNA GROUP
PTY LTD

BRENDAN MCKENNA
EARTHMOVING

MCKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

TRUCK & TRAILER ANNUAL INSPECTION

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

No. AS 204

Day FRIDAY
Date 5 / 05 / 17

Registration Number:	Make and Body Type:	Klms:	Unit No.:
161 TOS	ISUZU	31427	MCK40

Note: Cross out whichever is not applicable



Satisfactory



Defective

LIGHTING EQUIPMENT		SEAT BELTS		MOUNTINGS	
Battery Cradle/Security	☒	Fitted as required	☒	Engine	☒
Headlights/Auxiliary Lights	☒	Operation	☒	Transmission	☒
Park Lights	☒	Webbing/Fittings	☒	Body	☒
Tail Lights	☒	Anchorage	☒	STEERING	
Break Lights	☒	MUDGUARDS/MUDFLAPS		Free Play/Seals	☒
Reflectors/Marker Plates	☒	Fitted as Required	☒	Steering Box/Pitman Arm	☒
Clearance Lights	☒	Spray Suppression		Arms/Linkages	☒
Number Plate Light	☒	SIDE & BODY PANELS		King Pins/Bushes	☒
Reversing Light	☒	Cracks/Security	☒	Steering Wheel	☒
TURN SIGNALS		Corrosion/Damage	☒	SUSPENSION	
Operation	☒	FITTINGS & PROTRUSIONS		Shock Absorbers	☒
Colour	☒	Corrosion/Damage	☒	Cross Members	☒
Visibility	☒	Door/Bonnet/Catches	☒	Axles	☒
WARNING DEVICE		Rear Vision Mirrors	☒	Springs/U Bolts	☒
Control	☒	Body Fittings/Bumper Bars	☒	Air Bags/Air Suspension	☒
Audibility	☒	EXHAUST SYSTEM		Hangers/Pins/Bushes	☒
WIPERS/WASHERS		Leaks/Design/Security	☒	Bolts/Locknuts/Pins	☒
Blades/Insert	☒	Emission	☒	WHEELS & TYRES	
Controls/Motor	☒	UNDER BODY & CHASSIS		Wheels/Security	☒
GLAZING		Cracks/Security/Corrosion	☒	Tyres	☒
Material/Visibility	☒	OIL LEAKS		Wheel Bearings	☒
Window Operation	☒	Engine	☒	BRAKING SYSTEM	
SEATS		Transmission	☒	Service Brake	☒
Mounting/Construction	☒	Differential/s	☒	Park Brake	☒
Fitting/Operation	☒	Steering/Accessories	☒	TOW COUPLINGS	
Condition	☒	AIR SYSTEM		King Pin/Skid Plate/Auto	☒
SPEED LIMITER		Leaks/Contamination	☒	Turntable/Ringfeeder/Ball Race	☒
Speed Limiter operational and has not been tampered with	☒	Breakaway/Protection Valve	☒	Tow Eye/Draw Bar/Safety Chains	

DETAILS OF ITEMS REJECTED

CERTIFICATION

I certify the above information is true and that the vehicle is in a safe and thoroughly serviceable condition

Mechanic's Name: ANDREW Mechanic's Signature: A. Bremitt Date: 5 / 05 / 17

OFFICE USE ONLY Entered By: Jos Signature: [Signature] Date: 23 / 11 / 18



McKENNA GROUP
PTY LTD

BRENDAN McKENNA
EARTHMOVING

McKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

SERVICE REPORT

No. S 2191

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

Day FRIDAY
Date 21/10/16

Machine: <u>ISUZU</u>	Hours:
Rego: <u>161 TOS</u>	Klms: <u>28 907</u>
Plant: <u>TIPPER</u>	Unit No.: <u>mck 40</u>

☒ A SERVICE CHECKLIST

Due: Weekly or 5,000 to 8,000kms

		NOTES	
Check Fault Repair Log and carry out necessary repairs.	☒	Inspect brake lining wear/travel and adjust if required.	☒
Grease all lubrication points.	☒	Check brake system for leaks (service and maxi).	☒
Lift cab/bonnet, grease pivots, check condition and tension of belts.	☒	Drain condensation from air tanks.	☒
Check power steering for fluid levels and leaks.	☒	Check steering joints and linkages.	☒
Check/top up engine oil and coolant level.	☒	Inspect for any obvious faults in suspension, structure or bodywork.	☒
Check transmission and differential for fluid levels and leaks.	☒	Visual check of airbag suspension where fitted.	☒
Check driveline and universal joints.	☒	Inspect wheel nuts and wheels for security, tyres for tread and inflation.	☒
Check all lights and reflectors.	☒	Check number plates, all labels for due date condition and security.	☒
Check horn, instruments, gauges, wipers and washers.	☒	Check for visible exhaust emissions and lack of engine power.	☒
Check battery terminals and security.	☒	Note numbers of fault repairs rectified -	☒

TRAILER

Grease all lubrication points		Inspect for any obvious faults in suspension, structure or bodywork.	
Inspect brake lining wear/travel and adjust if required.		Visual check of airbag suspension where fitted.	
Check all lights and reflectors		Check number plate, and all labels due date, condition and security	
Check condition of air lines and electrical cable			
Inspect wheel nuts and wheels for security, tyres for tread and inflation		Note numbers of fault repairs rectified -	

☒ B SERVICE CHECKLIST Including items from Checklist A

TRUCK & TRAILER (Approx 20,000kms)

		NOTES	
All components of "A" Service.	☒	Check front steering hub oil level	☒
Change engine oil and filters.	☒	Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.	☒
Change fuel filters and bleed and check for leaks.	☒	Replace or clean air cleaner as required.	☒
Test coolant and change water filters if required	☒	Check trailer breakaway and maxi system	☒
Check battery electrolyte level, terminals and security	☒	Note numbers of fault repairs rectified -	
Check clutch linkage, clutch brake operation and adjustment	☒		

☒ C SERVICE CHECKLIST Including items from Checklist A and B

TRUCK & TRAILER (Approx 200,000kms or annually)

		NOTES	
All components of "A" and "B" Services.	☒	Change PTO Hydraulic filters.	☒
Change power steering oil and filter.	☒	Service air dryers where applicable.	☒
Change transmission oil and filter (300,000kms for Synthetic Oil).	☒	Re-torque all "U" bolts and cross members.	☒
Change differential oil and filter.	☒	Note numbers of fault repairs rectified -	
Change oil in oil filled wheel bearings and check other wheel bearings.	☒		

The person completing the service is to print their name and sign.

Name: LAUREN FLOYD Signature: [Signature] Date: 21/10/16

OFFICE USE ONLY Entered By:
Name: A. McKenna Signature: [Signature] Date: 26/10/16



McKENNA GROUP
PTY LTD

BRENDAN McKENNA
EARTHMOVING

McKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

TRUCK & TRAILER
ANNUAL INSPECTION

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

No. AS **051**

Day **THURSDAY**
Date **5/5/16**

Registration Number:	Make and Body Type:	Kilms:	Unit No.:
161 TOS	ISUZU TIPPER	23628	mck40

Note: Cross out whichever is not applicable



Satisfactory



Defective

LIGHTING EQUIPMENT		SEAT BELTS		MOUNTINGS	
Battery Cradle/Security	☒	Fitted as required	☒	Engine	☒
Headlights/Auxiliary Lights	☒	Operation	☒	Transmission	☒
Park Lights	☒	Webbing/Fittings	☒	Body	☒
Tail Lights	☒	Anchorage	☒	STEERING	
Break Lights	☒	MUDGUARDS/MUDFLAPS		Free Play/Seals	☒
Reflectors/Marker Plates	☒	Fitted as Required	☒	Steering Box/Pitman Arm	☒
Clearance Lights	☒	Spray Suppression	☒	Arms/Linkages	☒
Number Plate Light	☒	SIDE & BODY PANELS		King Pins/Bushes	☒
Reversing Light	☒	Cracks/Security	☒	Steering Wheel	☒
TURN SIGNALS		Corrosion/Damage	☒	SUSPENSION	
Operation	☒	FITTINGS & PROTRUSIONS		Shock Absorbers	☒
Colour	☒	Corrosion/Damage	☒	Cross Members	☒
Visibility	☒	Door/Bonnet/Catches	☒	Axles	☒
WARNING DEVICE		Rear Vision Mirrors	☒	Springs/U Bolts	☒
Control	☒	Body Fittings/Bumper Bars	☒	Air Bags/Air Suspension	☒
Audibility	☒	EXHAUST SYSTEM		Hangers/Pins/Bushes	☒
WIPERS/WASHERS		Leaks/Design/Security	☒	Bolts/Locknuts/Pins	☒
Blades/Insert	☒	Emission	☒	WHEELS & TYRES	
Controls/Motor	☒	UNDER BODY & CHASSIS		Wheels/Security	☒
GLAZING		Cracks/Security/Corrosion	☒	Tyres	☒
Material/Visibility	☒	OIL LEAKS		Wheel Bearings	☒
Window Operation	☒	Engine	☒	BRAKING SYSTEM	
SEATS		Transmission	☒	Service Brake	☒
Mounting/Construction	☒	Differential/s	☒	Park Brake	☒
Fitting/Operation	☒	Steering/Accessories	☒	TOW COUPLINGS	
Condition	☒	AIR SYSTEM		King Pin/Skid Plate/Auto	☒
SPEED LIMITER		Leaks/Contamination	☒	Turntable/Ringfeeder/Ball Race	☒
Speed Limiter operational and has not been tampered with	☒	Breakaway/Protection Valve	☒	Tow Eye/Draw Bar/Safety Chains	☒

DETAILS OF ITEMS REJECTED

Notes

CERTIFICATION

I certify the above information is true and that the vehicle is in a safe and thoroughly serviceable condition

Mechanic's Name: **LAWRENCE FLORE** Mechanic's Signature: **[Signature]** Date: **5/5/16**

OFFICE USE ONLY Entered By:

Name: **Angela McKenna** Signature: **[Signature]** D:



McKENNA GROUP
PTY LTD

■ BRENDAN McKENNA
EARTHMOVING

■ McKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

SERVICE REPORT

No. S 2100

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

Day THURS
Date 5/5/16

Machine:	15424	Hours:	
Rego:	161 TOS	Klms:	23628
Plant:	TIPPER	Unit No.:	McK40

REPLACED NUMBER PLATE LIGHTS

☐ A SERVICE CHECKLIST

Due : Weekly or 5,000 to 8,000kms



NOTES



Check Fault Repair Log and carry out necessary repairs.	☒	Inspect brake lining wear/travel and adjust if required.	
Grease all lubrication points.		Check brake system for leaks (service and maxi).	
Lift cab/bonnet, grease pivots, check condition and tension of belts.		Drain condensation from air tanks.	
Check power steering for fluid levels and leaks.		Check steering joints and linkages.	
Check/top up engine oil and coolant level.		Inspect for any obvious faults in suspension, structure or bodywork.	
Check transmission and differential for fluid levels and leaks.		Visual check of airbag suspension where fitted.	
Check driveline and universal joints.		Inspect wheel nuts and wheels for security, tyres for tread and inflation.	
Check all lights and reflectors.		Check number plates, all labels for due date condition and security.	
Check horn, instruments, gauges, wipers and washers.		Check for visible exhaust emissions and lack of engine power.	
Check battery terminals and security.		Note numbers of fault repairs rectified -	

TRAILER

NOTES

Grease all lubrication points		Inspect for any obvious faults in suspension, structure or bodywork.	
Inspect brake lining wear/travel and adjust if required.		Visual check of airbag suspension where fitted.	
Check all lights and reflectors		Check number plate, and all labels due date, condition and security	
Check condition of air lines and electrical cable			
Inspect wheel nuts and wheels for security, tyres for tread and inflation		Note numbers of fault repairs rectified -	

☐ B SERVICE CHECKLIST Including items from Checklist A

TRUCK & TRAILER (Approx 20,000kms)

NOTES

All components of "A" Service.		Check front steering hub oil level	
Change engine oil and filters.		Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.	
Change fuel filters and bleed and check for leaks.		Replace or clean air cleaner as required.	
Test coolant and change water filters if required		Check trailer breakaway and maxi system	
Check battery electrolyte level, terminals and security		Note numbers of fault repairs rectified -	
Check clutch linkage, clutch brake operation and adjustment			

☐ C SERVICE CHECKLIST Including items from Checklist A and B

TRUCK & TRAILER (Approx 200,000kms or annually)

NOTES

All components of "A" and "B" Services.		Change PTO Hydraulic filters.	
Change power steering oil and filter.		Service air dryers where applicable.	
Change transmission oil and filter (300,000kms for Synthetic Oil).		Re-torque all "U" bolts and cross members.	
Change differential oil and filter.			
Change oil in oil filled wheel bearings and check other wheel bearings.		Note numbers of fault repairs rectified -	

The person completing the service is to print their name and sign.

Name: LAURE FLORIO Signature: [Signature] Date: 5/5/16

OFFICE USE ONLY Entered By:
Name: Angela McKenna Signature: [Signature] Date: 24/5/16



McKENNA GROUP
PTY LTD

BRENDAN MCKENNA
EARTHMOVING

McKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

SERVICE REPORT

No. S 2085

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

Day TUES
Date 15/3/16

Machine:	<u>15424</u>	Hours:	
Rego:	<u>161 TOS</u>	Klms:	<u>23 255</u>
Plant:	<u>TIPPER</u>	Unit No.:	<u>mck 60</u>

☐ A SERVICE CHECKLIST

Due : Weekly or 5,000 to 8,000kms

*REMOVED INT FAN AND FILTERS
CLEANED OUT AS FAN NOT OPERATING
PROPERLY*

NOTES

Check Fault Repair Log and carry out necessary repairs.		Inspect brake lining wear/travel and adjust if required.	
Grease all lubrication points.		Check brake system for leaks (service and maxi).	
Lift cab/bonnet, grease pivots, check condition and tension of belts.		Drain condensation from air tanks.	
Check power steering for fluid levels and leaks.		Check steering joints and linkages.	
Check/top up engine oil and coolant level.		Inspect for any obvious faults in suspension, structure or bodywork.	
Check transmission and differential for fluid levels and leaks.		Visual check of airbag suspension where fitted.	
Check driveline and universal joints.		Inspect wheel nuts and wheels for security, tyres for tread and inflation.	
Check all lights and reflectors.		Check number plates, all labels for due date condition and security.	
Check horn, instruments, gauges, wipers and washers.		Check for visible exhaust emissions and lack of engine power.	
Check battery terminals and security.		Note numbers of fault repairs rectified -	

TRAILER

NOTES

Grease all lubrication points		Inspect for any obvious faults in suspension, structure or bodywork.	
Inspect brake lining wear/travel and adjust if required.		Visual check of airbag suspension where fitted.	
Check all lights and reflectors		Check number plate, and all labels due date, condition and security	
Check condition of air lines and electrical cable			
Inspect wheel nuts and wheels for security, tyres for tread and inflation		Note numbers of fault repairs rectified -	

☐ B SERVICE CHECKLIST Including items from Checklist A

TRUCK & TRAILER (Approx 20,000klm)

NOTES

All components of "A" Service.		Check front steering hub oil level	
Change engine oil and filters.		Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.	
Change fuel filters and bleed and check for leaks.		Replace or clean air cleaner as required.	
Test coolant and change water filters if required		Check trailer breakaway and maxi system	
Check battery electrolyte level, terminals and security		Note numbers of fault repairs rectified -	
Check clutch linkage, clutch brake operation and adjustment			

☐ C SERVICE CHECKLIST Including items from Checklist A and B

TRUCK & TRAILER (Approx 200,000kms or annually)

NOTES

All components of "A" and "B" Services.		Change PTO Hydraulic filters.	
Change power steering oil and filter.		Service air dryers where applicable.	
Change transmission oil and filter (300,000klm for Synthetic Oil).		Re-torque all "U" bolts and cross members.	
Change differential oil and filter.			
Change oil in oil filled wheel bearings and check other wheel bearings.		Note numbers of fault repairs rectified -	

The person completing the service is to print their name and sign.

Name: LAURA FRANK Signature: [Signature] Date: 15/3/16

OFFICE USE ONLY Entered By:
Name: Jos Rohl Signature: [Signature] Date: 22/3/16



McKENNA GROUP
PTY LTD

BRENDAN McKENNA
EARTHMOVING

McKENNA HAULAGE

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

SERVICE REPORT

No. S 2030

11 Montego Court
Eatons Hill | QLD | 4037
ABN 35 108 043 312

Day wkd
Date 15 / 7 / 15

Machine:	15424.	Hours:	
Rego:	161 TOS	Klms:	15 736
Plant:	TIPPER.	Unit No.:	

☐ A SERVICE CHECKLIST

Due : Weekly or 5,000 to 8,000kms

		NOTES	
Check Fault Repair Log and carry out necessary repairs.	✓	Replace LF PARK BULB.	✓
Grease all lubrication points.	✓	Inspect brake lining wear/travel and adjust if required.	✓
Lift cab/bonnet, grease pivots, check condition and tension of belts.	✓	Check brake system for leaks (service and maxi).	✓
Check power steering for fluid levels and leaks.	✓	Drain condensation from air tanks.	✓
Check top up engine oil and coolant level.	✓	Check steering joints and linkages.	✓
Check transmission and differential for fluid levels and leaks.	✓	Inspect for any obvious faults in suspension, structure or bodywork.	✓
Check driveline and universal joints.	✓	Visual check of airbag suspension where fitted.	✓
Check all lights and reflectors.	✓	Inspect wheel nuts and wheels for security, tyres for tread and inflation.	✓
Check horn, instruments, gauges, wipers and washers.	✓	Check number plates, all labels for due date condition and security.	✓
Check battery terminals and security.	✓	Check for visible exhaust emissions and lack of engine power.	✓
		Note numbers of fault repairs rectified -	1

TRAILER

		NOTES	
Grease all lubrication points		Inspect for any obvious faults in suspension, structure or bodywork.	
Inspect brake lining wear/travel and adjust if required.		Visual check of airbag suspension where fitted.	
Check all lights and reflectors		Check number plate, and all labels due date, condition and security	
Check condition of air lines and electrical cable			
Inspect wheel nuts and wheels for security, tyres for tread and inflation		Note numbers of fault repairs rectified -	

☐ B SERVICE CHECKLIST Including items from Checklist A

TRUCK & TRAILER (Approx 20,000klm)

		NOTES	
All components of "A" Service.	✓	Check front steering hub oil level	✓
Change engine oil and filters.	✓	Check wear/movement in pitman arm, drag arm, tie rods and spring shackles.	✓
Change fuel filters and bleed and check for leaks.	✓	Replace or clean air cleaner as required.	✓
Test coolant and change water filters if required	✓	Check trailer breakaway and maxi system	✓
Check battery electrolyte level, terminals and security	✓	Note numbers of fault repairs rectified -	
Check clutch linkage, clutch brake operation and adjustment	✓		

☐ C SERVICE CHECKLIST Including items from Checklist A and B

TRUCK & TRAILER (Approx 200,000kms or annually)

		NOTES	
All components of "A" and "B" Services.		Change PTO Hydraulic filters.	
Change power steering oil and filter.		Service air dryers where applicable.	
Change transmission oil and filter (300,000klm for Synthetic Oil).		Re-torque all "U" bolts and cross members.	
Change differential oil and filter.			
Change oil in oil filled wheel bearings and check other wheel bearings.		Note numbers of fault repairs rectified -	

The person completing the service is to print their name and sign.

Name: LAWREN FLOYD Signature: [Signature] Date: 15 / 7 / 15
OFFICE USE ONLY Entered By: [Signature]
Name: [Signature] Signature: [Signature] Date: 19 / 7 / 15



BRENDAN MCKENNA EARTHMOVING

11 Montego Court Eatons Hill Qld 4037
Phone: 0417 710 806 Fax: (07) 3264 5661
Email: brendan.mckenna1@bigpond.com

MCKENNA HAULAGE

11 Montego Court Eatons Hill Qld 4037
Phone: 0417 710 806 Fax: (07) 3264 5661
Email: brendan.mckenna1@bigpond.com

Machine: 1 SUZUKI
Rego: MCK42
Hours: _____
Klms: 366

SERVICE REPORT

No. S 0674

Day: WED

Date: 5/3/14

Description of Service: FIT 2 WAY RADIO
WITH POWER INVERTER.

✓ Entered
13/3/14
JR

OFFICE USE ONLY

Entered by: _____
Signed: _____
Date: 1/1

SERVICE TECHNICIAN

Serviced by LAUREN FORD
Signed by: LRF
Date: 5/3/14



BRENDAN McKENNA
EARTHMOVING PTY LTD

BRENDAN McKENNA EARTHMOVING PTY LTD

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 94 163 887 563

Docket No. **PS-103732**

Day **Thursday**

Date **09/10/2025**

DAILY PLANT INSPECTION CHECKLIST

PLANT OPERATOR DAILY SAFETY CHECKLIST: Operators are required to check the following items before commencing work. These records form the basis of a plant maintenance procedure and will be subject to random inspection.

☐ B Double	☐ Excavator (14t)	☐ Low Loader	☐ Roller-Flat
☐ Bobcat	☐ Excavator (22t)	☐ Moxy (30t)	☐ Roller-Multi
☒ Combo	☐ Excavator (30t)	☐ Moxy (40t)	☐ Scraper
☐ Dozer (D6)	☐ Excavator (48t)	☐ Tractor	☐ Semi Trailer
☐ Dozer (D7)	☐ GPS	☐ Mulcher 175	☐ Side Tipper
☐ Dozer (D8)	☐ Grader 140H	☐ Mulcher 300	☐ Tandem Tipper
☐ End Loader	☐ Grader 140M	☐ Positrack	☐ Truck & Dog
☐ Excavator (5t)	☐ Grader 150 AWD	☐ Quadtrac	☐ Water Truck
☐ Excavator (8t)	☐ Labour	☐ Roller-Drawn	☒ Other: _____
MACHINE REGO NO.:	161TOS	TRAILER REGO NO.:	
MCK UNIT NO.:	40	HOURLY METRE/ KM READING:	151032km

☒ OK, No obvious defect ☒ Fault identified, use report below ☐ N/A Item not applicable to machine or operator

BEFORE COMMENCING, OPERATORS CHECK

Cabin - Access, egress seating, seatbelts, loose objects, controls, ropes or fops	OK	Misc - Air con, fire extinguisher	OK
Visibility - Windscreen, windows, wipers, washers, mirrors for security damage & grime	OK	Damage to - Panels/guards - Cracks to chassis/frame/body, Structure & body work - all panels & structural members secure	OK
Electrical System - Lights, amber beacon, horn, rev travel alarm, all reflectors & lenses	OK	Wheels, tyres, tracks - Wear/tension/pressure, thread integrity & wheel security	OK
Hydraulics - Rams, hoses, leaks, wear	OK	Hitch (safety pin) - Wear	N/A
Leaks - Engine, transmission, final drives, cooling systems, fuel, air	OK	Articulated joint/linkage	N/A
Brakes - Emergency & service, break failure indicator, pressure/vacuum gauges	OK	Plant security	OK
Compulsory signs, reflective tape, reflectors	OK	Bleed off contaminants from air tanks	OK
Tow/Couplings/Drawbars for security & integrity	OK	NHVAS Label fitted, not obscured, not damaged	OK
NHVAS Interception Book in vehicle	OK		

DETAILS OF FAULTS OR DEFECTS AND ACTION TAKEN:

The individual who carries out the check must understand that he or she is certifying the vehicle is safe to the limits of the inspection when the vehicle leaves the yard or depot.

Operator Name: **Trever** Signature:  Date: **09/10/2025**



BRENDAN McKENNA
EARTHMOVING PTY LTD

BRENDAN McKENNA EARTHMOVING PTY LTD

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 94 163 887 563

Docket No. **PS-103531**

Day Tuesday
Date 02/09/2025

DAILY PLANT INSPECTION CHECKLIST

PLANT OPERATOR DAILY SAFETY CHECKLIST: Operators are required to check the following items before commencing work. These records form the basis of a plant maintenance procedure and will be subject to random inspection.

☐ B Double	☐ Excavator (14t)	☐ Low Loader	☐ Roller-Flat
☐ Bobcat	☐ Excavator (22t)	☐ Moxy (30t)	☐ Roller-Multi
☐ Combo	☐ Excavator (30t)	☐ Moxy (40t)	☐ Scraper
☐ Dozer (D6)	☐ Excavator (48t)	☐ Tractor	☐ Semi Trailer
☐ Dozer (D7)	☐ GPS	☐ Mulcher 175	☐ Side Tipper
☐ Dozer (D8)	☐ Grader 140H	☐ Mulcher 300	☐ Tandem Tipper
☐ End Loader	☐ Grader 140M	☐ Positrac	☐ Truck & Dog
☐ Excavator (5t)	☐ Grader 150 AWD	☐ Quadtrac	☐ Water Truck
☐ Excavator (8t)	☐ Labour	☐ Roller-Drawn	☒ Other: _____

MACHINE REGO NO.:	161tos	TRAILER REGO NO.:	
MCK UNIT NO.:	40	HOURLY METRE/ KM READING:	148802

☒ OK, No obvious defect	☒ Fault identified, use report below	☐ N/A Item not applicable to machine or operator
---	--	---

BEFORE COMMENCING, OPERATORS CHECK			
Cabin - Access, egress seating, seatbelts, loose objects, controls, ropes or fops	OK	Misc - Air con, fire extinguisher	OK
Visibility - Windscreen, windows, wipers, washers, mirrors for security damage & grime	OK	Damage to - Panels/guards - Cracks to chassis/frame/body, Structure & body work - all panels & structural members secure	OK
Electrical System - Lights, amber beacon, horn, rev travel alarm, all reflectors & lenses	OK	Wheels, tyres, tracks - Wear/tension/pressure, thread integrity & wheel security	OK
Hydraulics - Rams, hoses, leaks, wear	OK	Hitch (safety pin) - Wear	OK
Leaks - Engine, transmission, final drives, cooling systems, fuel, air	OK	Articulated joint/linkage	IN/A
Brakes - Emergency & service, break failure indicator, pressure/vacuum gauges	OK	Plant security	OK
Compulsory signs, reflective tape, reflectors	OK	Bleed off contaminants from air tanks	OK
Tow/Couplings/Drawbars for security & integrity	OK	NHVAS Label fitted, not obscured, not damaged	IN/A
NHVAS Interception Book in vehicle	IN/A		

DETAILS OF FAULTS OR DEFECTS AND ACTION TAKEN:

The individual who carries out the check must understand that he or she is certifying the vehicle is safe to the limits of the inspection when the vehicle leaves the yard or depot.

Operator Name: Billy Penwarden Signature: Date: 02/09/2025



BRENDAN McKENNA
EARTHMOVING PTY LTD

BRENDAN McKENNA EARTHMOVING PTY LTD

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 94 163 887 563

Docket No. **PS-103127**

Day **Thursday**

Date **29/05/2025**

DAILY PLANT INSPECTION CHECKLIST

PLANT OPERATOR DAILY SAFETY CHECKLIST: Operators are required to check the following items before commencing work. These records form the basis of a plant maintenance procedure and will be subject to random inspection.

☐ B Double	☐ Excavator (14t)	☐ Low Loader	☐ Roller-Flat
☐ Bobcat	☐ Excavator (22t)	☐ Moxy (30t)	☐ Roller-Multi
☐ Combo	☐ Excavator (30t)	☐ Moxy (40t)	☐ Scraper
☐ Dozer (D6)	☐ Excavator (48t)	☐ Tractor	☐ Semi Trailer
☐ Dozer (D7)	☐ GPS	☐ Mulcher 175	☐ Side Tipper
☐ Dozer (D8)	☐ Grader 140H	☐ Mulcher 300	☐ Tandem Tipper
☐ End Loader	☐ Grader 140M	☐ Positrac	☐ Truck & Dog
☐ Excavator (5t)	☐ Grader 150 AWD	☐ Quadtrac	☐ Water Truck
☐ Excavator (8t)	☐ Labour	☐ Roller-Drawn	☒ Other: Spray truck
MACHINE REGO NO.:	161tos	TRAILER REGO NO.:	0
MCK UNIT NO.:	0	HOURLY METRE/ KM READING:	144020



OK, No obvious defect



Fault identified, use report below



N/A Item not applicable to machine or operator

BEFORE COMMENCING, OPERATORS CHECK

Cabin - Access, egress seating, seatbelts, loose objects, controls, ropes or fops	OK	Misc - Air con, fire extinguisher	OK
Visibility - Windscreen, windows, wipers, washers, mirrors for security damage & grime	OK	Damage to - Panels/guards - Cracks to chassis/frame/body. Structure & body work - all panels & structural members secure	OK
Electrical System - Lights, amber beacon, horn, rev travel alarm, all reflectors & lenses	OK	Wheels, tyres, tracks - Wear/tension/pressure, thread integrity & wheel security	OK
Hydraulics - Rams, hoses, leaks, wear	OK	Hitch (safety pin) - Wear	OK
Leaks - Engine, transmission, final drives, cooling systems, fuel, air	OK	Articulated joint/linkage	N/A
Brakes - Emergency & service, break failure indicator, pressure/vacuum gauges	OK	Plant security	OK
Compulsory signs, reflective tape, reflectors	OK	Bleed off contaminants from air tanks	OK
Tow/Couplings/Drawbars for security & integrity	OK	NHVAS Label fitted, not obscured, not damaged	OK
NHVAS Interception Book in vehicle	OK		

DETAILS OF FAULTS OR DEFECTS AND ACTION TAKEN:

The individual who carries out the check must understand that he or she is certifying the vehicle is safe to the limits of the inspection when the vehicle leaves the yard or depot.

Operator Name: **Peter Bergin**

Signature:

Date: **29/05/2025**



BRENDAN McKENNA
EARTHMOVING PTY LTD

BRENDAN McKENNA EARTHMOVING PTY LTD

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 94 163 887 563

Docket No. **PS-102481**

Day Monday
Date 21/10/2024

DAILY PLANT INSPECTION CHECKLIST

PLANT OPERATOR DAILY SAFETY CHECKLIST: Operators are required to check the following items before commencing work. These records form the basis of a plant maintenance procedure and will be subject to random inspection.

☐ B Double	☐ Excavator (14t)	☐ Low Loader	☐ Roller-Flat
☐ Bobcat	☐ Excavator (22t)	☐ Moxy (30t)	☐ Roller-Multi
☐ Combo	☐ Excavator (30t)	☐ Moxy (40t)	☐ Scraper
☐ Dozer (D6)	☐ Excavator (48t)	☐ Tractor	☐ Semi Trailer
☐ Dozer (D7)	☐ GPS	☐ Mulcher 175	☐ Side Tipper
☐ Dozer (D8)	☐ Grader 140H	☐ Mulcher 300	☐ Tandem Tipper
☐ End Loader	☐ Grader 140M	☐ Positrack	☐ Truck & Dog
☐ Excavator (5t)	☐ Grader 150 AWD	☐ Quadtrac	☐ Water Truck
☐ Excavator (8t)	☐ Labour	☐ Roller-Drawn	☐ Other: _____

MACHINE REGO NO.:	161-TOS	TRAILER REGO NO.:	N/A
MCK UNIT NO.:	MCK0	HOURLY METRE/ KM READING:	137560km

☒ OK, No obvious defect
 ☒ Fault identified, use report below
 ☒ N/A Item not applicable to machine or operator

BEFORE COMMENCING, OPERATORS CHECK			
Cabin - Access, egress seating, seatbelts, loose objects, controls, rOPS or fOPS	OK	Misc - Air con, fire extinguisher	X
Visibility - Windscreen, windows, wipers, washers, mirrors for security damage & grime	OK	Damage to - Panels/guards - Cracks to chassis/frame/body, Structure & body work - all panels & structural members secure	OK
Electrical System - Lights, amber beacon, horn, rev travel alarm, all reflectors & lenses	OK	Wheels, tyres, tracks - Wear/tension/pressure, thread integrity & wheel security	OK
Hydraulics - Rams, hoses, leaks, wear	OK	Hitch (safety pin) - Wear	IV/IV
Leaks - Engine, transmission, final drives, cooling systems, fuel, air	OK	Articulated joint/linkage	IV/IV
Brakes - Emergency & service, break failure indicator, pressure/vacuum gauges	OK	Plant security	OK
Compulsary signs, reflective tape, reflectors	OK	Bleed off contaminants from air tanks	OK
Tow/Couplings/Drawbars for security & integrity	IV/IV	NHVAS Label fitted, not obscured, not damaged	OK
NHVAS Interception Book in vehicle	OK		

DETAILS OF FAULTS OR DEFECTS AND ACTION TAKEN:

Air-conditioner and fan not working

The individual who carries out the check must understand that he or she is certifying the vehicle is safe to the limits of the inspection when the vehicle leaves the yard or depot.

Operator Name: Robert Brandt Signature: Robert Date: 21/10/2024



BRENDAN MCKENNA
EARTHMOVING PTY LTD

BRENDAN MCKENNA EARTHMOVING PTY LTD

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 94 163 887 563

Docket No. PS-102159

Day Wednesday

Date 03/07/2024

DAILY PLANT INSPECTION CHECKLIST

PLANT OPERATOR DAILY SAFETY CHECKLIST: Operators are required to check the following items before commencing work. These records form the basis of a plant maintenance procedure and will be subject to random inspection.

☐ B Double ☐ Bobcat ☐ Combo ☐ Dozer (D6) ☐ Dozer (D7) ☐ Dozer (D8) ☐ End Loader ☐ Excavator (5t) ☐ Excavator (8t)	☐ Excavator (14t) ☐ Excavator (22t) ☐ Excavator (30t) ☐ Excavator (48t) ☐ GPS ☐ Grader 140H ☐ Grader 140M ☐ Grader 150 AWD ☐ Labour	☐ Low Loader ☐ Moxy (30t) ☐ Moxy (40t) ☐ Tractor ☐ Mulcher 175 ☐ Mulcher 300 ☐ Positrac ☐ Quadtrac ☐ Roller-Drawn	☐ Roller-Flat ☐ Roller-Multi ☐ Scraper ☐ Semi Trailer ☐ Side Tipper ☐ Tandem Tipper ☐ Truck & Dog ☐ Water Truck ☒ Other: Isuzu with spray tank
MACHINE REGO NO.:	161tos	TRAILER REGO NO.:	
MCK UNIT NO.:	40	HOURLY METRE/ KM READING:	135354



OK, No obvious defect



Fault identified, use report below



N/A Item not applicable to machine or operator

BEFORE COMMENCING, OPERATORS CHECK

Cabin - Access, egress seating, seatbelts, loose objects, controls, rops or fops	OK	Misc - Air con, fire extinguisher	OK
Visibility - Windscreen, windows, wipers, washers, mirrors for security damage & grime	OK	Damage to - Panels/guards - Cracks to chassis/frame/body, Structure & body work - all panels & structural members secure	OK
Electrical System - Lights, amber beacon, horn, rev travel alarm, all reflectors & lenses	OK	Wheels, tyres, tracks - Wear/tension/pressure, thread integrity & wheel security	OK
Hydraulics - Rams, hoses, leaks, wear	OK	Hitch (safety pin) - Wear	OK
Leaks - Engine, transmission, final drives, cooling systems, fuel, air	OK	Articulated joint/linkage	N/A
Brakes - Emergency & service, break failure indicator, pressure/vacuum gauges	OK	Plant security	OK
Compulsary signs, reflective tape, reflectors	OK	Bleed off contaminants from air tanks	OK
Tow/Couplings/Drawbars for security & integrity	OK	NHVAS Label fitted, not obscured, not damaged	OK
NHVAS Interception Book in vehicle	OK		

DETAILS OF FAULTS OR DEFECTS AND ACTION TAKEN:

The individual who carries out the check must understand that he or she is certifying the vehicle is safe to the limits of the inspection when the vehicle leaves the yard or depot.

Operator Name: Peter bergin

Signature:

Date: 03/07/2024



BRENDAN MCKENNA
EARTHMOVING PTY LTD

BRENDAN MCKENNA EARTHMOVING PTY LTD

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 94 163 887 563

Docket No. **PS-102069**

Day Monday
Date 17/06/2024

DAILY PLANT INSPECTION CHECKLIST

PLANT OPERATOR DAILY SAFETY CHECKLIST: Operators are required to check the following items before commencing work. These records form the basis of a plant maintenance procedure and will be subject to random inspection.

☐ B Double	☐ Excavator (14t)	☐ Low Loader	☐ Roller-Flat
☐ Bobcat	☐ Excavator (22t)	☐ Moxy (30t)	☐ Roller-Multi
☐ Combo	☐ Excavator (30t)	☐ Moxy (40t)	☐ Scraper
☐ Dozer (D6)	☐ Excavator (48t)	☐ Tractor	☐ Semi Trailer
☐ Dozer (D7)	☐ GPS	☐ Mulcher 175	☐ Side Tipper
☐ Dozer (D8)	☐ Grader 140H	☐ Mulcher 300	☒ Tandem Tipper
☐ End Loader	☐ Grader 140M	☐ Positrack	☐ Truck & Dog
☐ Excavator (5t)	☐ Grader 150 AWD	☐ Quadtrac	☐ Water Truck
☐ Excavator (8t)	☐ Labour	☐ Roller-Drawn	☐ Other: _____

MACHINE REGO NO.:	161tos	TRAILER REGO NO.:	
MCK UNIT NO.:	40	HOURLY METRE/ KM READING:	134456

☒ OK, No obvious defect	☒ Fault identified, use report below	☐ N/A Item not applicable to machine or operator
---	--	---

BEFORE COMMENCING, OPERATORS CHECK			
Cabin - Access, egress seating, seatbelts, loose objects, controls, ropes or fops	OK	Misc - Air con, fire extinguisher	OK
Visibility - Windscreen, windows, wipers, washers, mirrors for security damage & grime	OK	Damage to - Panels/guards - Cracks to chassis/frame/body, Structure & body work - all panels & structural members secure	OK
Electrical System - Lights, amber beacon, horn, rev travel alarm, all reflectors & lenses	OK	Wheels, tyres, tracks - Wear/tension/pressure, thread integrity & wheel security	OK
Hydraulics - Rams, hoses, leaks, wear	OK	Hitch (safety pin) - Wear	OK
Leaks - Engine, transmission, final drives, cooling systems, fuel, air	OK	Articulated joint/linkage	N/A
Brakes - Emergency & service, break failure indicator, pressure/vacuum gauges	OK	Plant security	OK
Compulsary signs, reflective tape, reflectors	OK	Bleed off contaminants from air tanks	OK
Tow/Couplings/Drawbars for security & integrity	OK	NHVAS Label fitted, not obscured, not damaged	OK
NHVAS Interception Book in vehicle	OK		

DETAILS OF FAULTS OR DEFECTS AND ACTION TAKEN:

The individual who carries out the check must understand that he or she is certifying the vehicle is safe to the limits of the inspection when the vehicle leaves the yard or depot.

Operator Name: Peter Bergin Signature: Date: 17/06/2024



BRENDAN McKENNA
EARTHMOVING PTY LTD

BRENDAN McKENNA EARTHMOVING PTY LTD

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 94 163 887 563

Docket No. **PS-101852**

Day **Thursday**

Date **09/05/2024**

DAILY PLANT INSPECTION CHECKLIST

PLANT OPERATOR DAILY SAFETY CHECKLIST: Operators are required to check the following items before commencing work. These records form the basis of a plant maintenance procedure and will be subject to random inspection.

☐ B Double	☐ Excavator (14t)	☐ Low Loader	☐ Roller-Flat
☐ Bobcat	☐ Excavator (22t)	☐ Moxy (30t)	☐ Roller-Multi
☐ Combo	☐ Excavator (30t)	☐ Moxy (40t)	☐ Scraper
☐ Dozer (D6)	☐ Excavator (48t)	☐ Tractor	☐ Semi Trailer
☐ Dozer (D7)	☐ GPS	☐ Mulcher 175	☐ Side Tipper
☐ Dozer (D8)	☐ Grader 140H	☐ Mulcher 300	☒ Tandem Tipper
☐ End Loader	☐ Grader 140M	☐ Positrack	☐ Truck & Dog
☐ Excavator (5t)	☐ Grader 150 AWD	☐ Quadtrac	☐ Water Truck
☐ Excavator (8t)	☐ Labour	☐ Roller-Drawn	☐ Other: _____
MACHINE REGO NO.:	161tos	TRAILER REGO NO.:	
MCK UNIT NO.:	40	HOURLY METRE/ KM READING:	132811



OK, No obvious defect



Fault identified, use report below



N/A Item not applicable to machine or operator

BEFORE COMMENCING, OPERATORS CHECK

Cabin - Access, egress seating, seatbelts, loose objects, controls, ropes or fops	OK	Misc - Air con, fire extinguisher	OK
Visibility - Windscreen, windows, wipers, washers, mirrors for security damage & grime	OK	Damage to - Panels/guards - Cracks to chassis/frame/body, Structure & body work - all panels & structural members secure	OK
Electrical System - Lights, amber beacon, horn, rev travel alarm, all reflectors & lenses	OK	Wheels, tyres, tracks - Wear/tension/pressure, thread integrity & wheel security	OK
Hydraulics - Rams, hoses, leaks, wear	OK	Hitch (safety pin) - Wear	OK
Leaks - Engine, transmission, final drives, cooling systems, fuel, air	OK	Articulated joint/linkage	OK
Brakes - Emergency & service, break failure indicator, pressure/vacuum gauges	OK	Plant security	OK
Compulsary signs, reflective tape, reflectors	OK	Bleed off contaminants from air tanks	OK
Tow/Couplings/Drawbars for security & integrity	OK	NHVAS Label fitted, not obscured, not damaged	OK
NHVAS Interception Book in vehicle	OK		

DETAILS OF FAULTS OR DEFECTS AND ACTION TAKEN:

The individual who carries out the check must understand that he or she is certifying the vehicle is safe to the limits of the inspection when the vehicle leaves the yard or depot.

Operator Name: **Peter Bergin**

Signature:

Date: **09/05/2024**



BRENDAN MCKENNA
EARTHMOVING PTY LTD

BRENDAN MCKENNA EARTHMOVING PTY LTD

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 94 163 887 563

Docket No. **PS-101773**

Day **Wednesday**

Date **17/04/2024**

DAILY PLANT INSPECTION CHECKLIST

PLANT OPERATOR DAILY SAFETY CHECKLIST: Operators are required to check the following items before commencing work. These records form the basis of a plant maintenance procedure and will be subject to random inspection.

☐ B Double	☐ Excavator (14t)	☐ Low Loader	☐ Roller-Flat
☐ Bobcat	☐ Excavator (22t)	☐ Moxy (30t)	☐ Roller-Multi
☐ Combo	☐ Excavator (30t)	☐ Moxy (40t)	☐ Scraper
☐ Dozer (D6)	☐ Excavator (48t)	☐ Tractor	☐ Semi Trailer
☐ Dozer (D7)	☐ GPS	☐ Mulcher 175	☐ Side Tipper
☐ Dozer (D8)	☐ Grader 140H	☐ Mulcher 300	☐ Tandem Tipper
☐ End Loader	☐ Grader 140M	☐ Positrack	☐ Truck & Dog
☐ Excavator (5t)	☐ Grader 150 AWD	☐ Quadtrac	☐ Water Truck
☐ Excavator (8t)	☐ Labour	☐ Roller-Drawn	☒ Other: Isuzu tipper

MACHINE REGO NO.:	161tos	TRAILER REGO NO.:	
MCK UNIT NO.:	40	HOURLY METRE/ KM READING:	130769

☒ OK, No obvious defect ☒ Fault identified, use report below ☒ N/A Item not applicable to machine or operator

BEFORE COMMENCING, OPERATORS CHECK

Cabin - Access, egress seating, seatbelts, loose objects, controls, rOPS or fOPS	OK	Misc - Air con, fire extinguisher	OK
Visibility - Windscreen, windows, wipers, washers, mirrors for security damage & grime	OK	Damage to - Panels/guards - Cracks to chassis/frame/body, Structure & body work - all panels & structural members secure	OK
Electrical System - Lights, amber beacon, horn, rev travel alarm, all reflectors & lenses	OK	Wheels, tyres, tracks - Wear/tension/pressure, thread integrity & wheel security	OK
Hydraulics - Rams, hoses, leaks, wear	OK	Hitch (safety pin) - Wear	OK
Leaks - Engine, transmission, final drives, cooling systems, fuel, air	OK	Articulated joint/linkage	OK
Brakes - Emergency & service, break failure indicator, pressure/vacuum gauges	OK	Plant security	OK
Compulsory signs, reflective tape, reflectors	OK	Bleed off contaminants from air tanks	OK
Tow/Couplings/Drawbars for security & integrity	OK	NHVAS Label fitted, not obscured, not damaged	OK
NHVAS Interception Book in vehicle	OK		

DETAILS OF FAULTS OR DEFECTS AND ACTION TAKEN:

The individual who carries out the check must understand that he or she is certifying the vehicle is safe to the limits of the inspection when the vehicle leaves the yard or depot.

Operator Name: **Jason adsett**

Signature:

Date: **17/04/2024**



BRENDAN MCKENNA
EARTHMOVING PTY LTD

BRENDAN MCKENNA EARTHMOVING PTY LTD

M 0417 710 806
F 07 3264 5661
E accounts@mckgroup.com.au

11 Montego Court
Eatons Hill | QLD | 4037
ABN 94 163 887 563

Docket No. PS-100968

Day Friday
Date 15/09/2023

DAILY PLANT INSPECTION CHECKLIST

PLANT OPERATOR DAILY SAFETY CHECKLIST: Operators are required to check the following items before commencing work. These records form the basis of a plant maintenance procedure and will be subject to random inspection.

☐ B Double	☐ Excavator (14t)	☐ Low Loader	☐ Roller-Flat
☐ Bobcat	☐ Excavator (22t)	☐ Moxy (30t)	☐ Roller-Multi
☐ Combo	☐ Excavator (30t)	☐ Moxy (40t)	☐ Scraper
☐ Dozer (D6)	☐ Excavator (48t)	☐ Tractor	☐ Semi Trailer
☐ Dozer (D7)	☐ GPS	☐ Mulcher 175	☐ Side Tipper
☐ Dozer (D8)	☐ Grader 140H	☐ Mulcher 300	☐ Tandem Tipper
☐ End Loader	☐ Grader 140M	☐ Positrack	☐ Truck & Dog
☐ Excavator (5t)	☐ Grader 150 AWD	☐ Quadtrac	☐ Water Truck
☐ Excavator (8t)	☐ Labour	☐ Roller-Drawn	☒ Other: Isuzu tipper
MACHINE REGO NO.:	161tos	TRAILER REGO NO.:	
MCK UNIT NO.:	40	HOURLY METRE/ KM READING:	122927

☒ OK, No obvious defect	☒ Fault identified, use report below	☐ N/A Item not applicable to machine or operator
---	--	---

BEFORE COMMENCING, OPERATORS CHECK			
Cabin - Access, egress seating, seatbelts, loose objects, controls, ropes or fops	OK	Misc - Air con, fire extinguisher	OK
Visibility - Windscreen, windows, wipers, washers, mirrors for security damage & grime	OK	Damage to - Panels/guards - Cracks to chassis/frame/body, Structure & body work - all panels & structural members secure	OK
Electrical System - Lights, amber beacon, horn, rev travel alarm, all reflectors & lenses	OK	Wheels, tyres, tracks - Wear/tension/pressure, thread integrity & wheel security	OK
Hydraulics - Rams, hoses, leaks, wear	OK	Hitch (safety pin) - Wear	OK
Leaks - Engine, transmission, final drives, cooling systems, fuel, air	OK	Articulated joint/linkage	OK
Brakes - Emergency & service, break failure indicator, pressure/vacuum gauges	OK	Plant security	OK
Compulsory signs, reflective tape, reflectors	OK	Bleed off contaminants from air tanks	OK
Tow/Couplings/Drawbars for security & integrity	OK	NHVAS Label fitted, not obscured, not damaged	OK
NHVAS Interception Book in vehicle	OK		

DETAILS OF FAULTS OR DEFECTS AND ACTION TAKEN:

The individual who carries out the check must understand that he or she is certifying the vehicle is safe to the limits of the inspection when the vehicle leaves the yard or depot.

Operator Name: Jason adsett Signature:  Date: 15/09/2023